Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiablisecure@yalic	70.00.111					
Service Status Det	ails : VE14352					
Priority:	Low					
Created By :	Admin - Apurva Vajaria					
Complaint Mob. No. :	9769202846					
Technician Name	Ravi Rajbhar		Technician Mobile :		8080922965	
Ticket Type :	Complain	Date & Time :	24-03-2025 02:21:23			
Vendor Details :						
Company Name/Client Name :	Momai Creation	Customer's Mobile :	9769202846		Name :	Navin Bhai
Address:			-			
Mumbai , , , , Mah	arashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:	1970 05:30:00 Type:				
Product Name:	CCTV					
Complain:	5 cameras off issue					
Technician Comment :	4 cmaera change against faulty and one cmaera remove and take to office navin sir cabin And all ok working done					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	4 cmaera change against faulty and one cmaera remove and take to office navin sir cabin And all ok working done					
Status History :	Date Time	Technician Name	Status]	Remark	Sign
	25-03-2025 03:35:20) Ravi Rajbhar	Completed	4 cmaera	change against	0 ./V
				faulty an remove a	d one cmaera and take to office cabin And all ok	(X/ Wings
	24-03-2025 06:40:40) Ravi Rajbhar	New	faulty an remove a navin sir	d one cmaera and take to office cabin And all ok	- Vino
	24-03-2025 06:40:40 24-03-2025 04:16:2°		New Work Pending	faulty an remove a navin sir working	d one cmaera and take to office cabin And all ok	-
		7 Ravi Rajbhar		faulty an remove a navin sir working	d one cmaera and take to office cabin And all ok done a not working. 3	-
Previous	24-03-2025 04:16:2	7 Ravi Rajbhar	Work Pending	faulty an remove a navin sir working 3 camera camera c	d one cmaera and take to office cabin And all ok done a not working. 3	-
Previous Complain History	24-03-2025 04:16:2° 24-03-2025 02:21:29	7 Ravi Rajbhar 9 Ravi Rajbhar Technician Name	Work Pending	faulty an remove a navin sir working 3 camera camera c	d one cmaera and take to office cabin And all ok done a not working. 3 sheking office. mark I biometric softwa	re install and