

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2627																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9702786668																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	New Installation	Date & Time :	27-01-2021 03:12:07																											
Vendor Details :																														
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	9702786668	Name :	Nazia																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	30-09-2020 12:00:00		Type :	Comprehensive																										
Product Name :	Fire																													
Complain :	Install LPG detector																													
Technician Comment :	gas leak detector installed and working ok.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	gas leak detector installed and working ok.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-01-2021 03:50:16</td><td>Atique Salmani</td><td>Completed</td><td>gas leak detector installed and working ok.</td><td></td></tr><tr><td>27-01-2021 03:12:22</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-01-2021 03:12:20</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-01-2021 03:12:07</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-01-2021 03:50:16	Atique Salmani	Completed	gas leak detector installed and working ok.		27-01-2021 03:12:22	Atique Salmani	New		-	27-01-2021 03:12:20	Atique Salmani	New		-	27-01-2021 03:12:07	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
28-01-2021 03:50:16	Atique Salmani	Completed	gas leak detector installed and working ok.																											
27-01-2021 03:12:22	Atique Salmani	New		-																										
27-01-2021 03:12:20	Atique Salmani	New		-																										
27-01-2021 03:12:07	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-08-2023 04:02:35</td><td>Ishwar Meena</td><td>(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.</td></tr><tr><td>15-07-2023 10:32:24</td><td>Atique Salmani</td><td>In Manju mam phone cctv online done working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-08-2023 04:02:35	Ishwar Meena	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.	15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.																
Date Time	Technician Name	Remark																												
03-08-2023 04:02:35	Ishwar Meena	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.																												
15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.																												