


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2680					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9702786668				
Technician Name :	Rishi Desai		Technician Mobile :	8369234074	
Ticket Type :	Complain	Date & Time :	09-02-2021 10:41:52		
Vendor Details :					
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	9702786668	Name :	Nazia
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	30-09-2020 12:00:00		Type :	Comprehensive	
Product Name :	Fire				
Complain :	survey				
Technician Comment :	<p>Womens Hospital *Ground Floor* 1. Reception lobby (Back) : Agni 4 zone Fire Alarm System . Zone 1 : Ground Floor Zone 2 : 1st Floor. Zone 3 : 2nd Floor. Zone 4 : 3rd Floor. AGNI SOUNDER RED : 1nos Ground Floor OT Complex : Smoke sensor - 3nos Ground Floor Lobby : Smoke sensor - 1nos Ground floor Sitting area : smoke sensor - 1 nos Ground floor Opposite Lift : MCP - 1nos CONSULTING ROOM A, B, C : Smoke sensor : 3 nos Respectively. *1st Floor* Floor Lobby : smoke sensor - 2nos Floor Lobby : MCP - 1nos Focus Room : smoke sensor - 1nos Passion Room : smoke sensor - 1nos Persistance room : smoke sensor - 1nos Commitment room : smoke snesor - 1nos Compassion room : smoke sensor - 1nos Courage room : smoke sensor - 1nos Potential room : smoke sensor - 1nos Purpose room : smoke sensor - 1nos Harmony room : smoke sensor - 1nos *2nd Floor* Floor Lobby : smoke sensor - 2nos Library : smoke sensor - 1nos Stores : smoke sensor - 1nos Ultrasound : smoke sensor - 1nos Doctors Lounge : smoke sensor : 1nos Lounge Gate : MCP - 1nos Lounge Lobby : smoke sensor : 2nos Dream room : smoke sensor - 1nos Discipline room : smoke sensor - 1nos Hungry room : Gas Leak Detector - 1nos *3rd Floor* Vision Room : smoke sensor - 1nos Lobby : MCP - 1nos Open Terrace : AGNI SOUNDER RED : 1nos Open terrace : smoke sensor - 1nos Cssid room : smoke sensor - 1nos Papa Ji office : smoke sensor : 1nos Mandir : smoke sensor - 1nos Lift Room : smoke sensor - 1nos Staff room : smoke sensor - 1nos Not visited many Rooms because of doctors restrictions as there are many patients checking and some are admitted. Ony Checked : Ground Floor lobby , Sitting area , 1st floor lobby , 2nd floor lobby , library, lounge lobby, Hungry, 3rd floor vision, lobby, open terrace ,Mainly information provided by Womens hospital staff person Total Devices :- Smoke sensors : 36nos Ground floor - 8nos 1st floor - 11nos 2nd floor - 10nos 3rd floor - 7nos Sounder : 2nos MCP : 4nos Gas leak detector : 1nos (Hungry Room 2nd floor)</p>				
Complain Operator :	Desktop - Apurva Vajaria				

Remark :	<p>Womens Hospital *Ground Floor* 1. Reception lobby (Back) : Agni 4 zone Fire Alarm System . Zone 1 : Ground Floor Zone 2 : 1st Floor. Zone 3 : 2nd Floor. Zone 4 : 3rd Floor. AGNI SOUNDER RED : 1nos Ground Floor OT Complex : Smoke sensor - 3nos Ground Floor Lobby : Smoke sensor - 1nos Ground floor Sitting area : smoke sensor - 1 nos Ground floor Opposite Lift : MCP - 1nos CONSULTING ROOM A, B, C : Smoke sensor : 3 nos Respectively. *1st Floor* Floor Lobby : smoke sensor - 2nos Floor Lobby : MCP - 1nos Focus Room : smoke sensor - 1nos Passion Room : smoke sensor - 1nos Persistance room : smoke sensor - 1nos Commitment room : smoke snesor - 1nos Compassion room : smoke sensor - 1nos Courage room : smoke sensor - 1nos Potential room : smoke sensor - 1nos Purpose room : smoke sensor - 1nos Harmony room : smoke sensor - 1nos *2nd Floor* Floor Lobby : smoke sensor - 2nos Library : smoke sensor - 1nos Stores : smoke sensor - 1nos Ultrasound : smoke sensor - 1nos Doctors Lounge : smoke sensor : 1nos Lounge Gate : MCP - 1nos Lounge Lobby : smoke sensor : 2nos Dream room : smoke sensor - 1nos Discipline room : smoke sensor - 1nos Hungry room : Gas Leak Detector - 1nos *3rd Floor* Vision Room : smoke sensor - 1nos Lobby : MCP - 1nos Open Terrace : AGNI SOUNDER RED : 1nos Open terrace : smoke sensor - 1nos Cssid room : smoke sensor - 1nos Papa Ji office : smoke sensor : 1nos Mandir : smoke sensor - 1nos Lift Room : smoke sensor - 1nos Staff room : smoke sensor - 1nos Not visited many Rooms because of doctors restrictions as there are many patients checking and some are admitted. Ony Checked : Ground Floor lobby , Sitting area , 1st floor lobby , 2nd floor lobby , library, lounge lobby, Hungry, 3rd floor vision, lobby, open terrace ,Mainly information provided by Womens hospital staff person Total Devices :- Smoke sensors : 36nos Ground floor - 8nos 1st floor - 11nos 2nd floor - 10nos 3rd floor - 7nos Sounder : 2nos MCP : 4nos Gas leak detector : 1nos (Hungry Room 2nd floor)</p>
-----------------	---

Status History :	Date Time	Technician Name	Status	Remark	Sign
	09-02-2021 02:19:46	RishiDesai	Completed	<p>Womens Hospital *Ground Floor* 1. Reception lobby (Back) : Agni 4 zone Fire Alarm System . Zone 1 : Ground Floor Zone 2 : 1st Floor. Zone 3 : 2nd Floor. Zone 4 : 3rd Floor. AGNI SOUNDER RED : 1nos Ground Floor OT Complex : Smoke sensor - 3nos Ground Floor Lobby : Smoke sensor - 1nos Ground floor Sitting area : smoke sensor - 1 nos Ground floor Opposite Lift : MCP - 1nos CONSULTING ROOM A, B, C : Smoke sensor : 3 nos Respectively. *1st Floor* Floor Lobby : smoke sensor - 2nos Floor Lobby : MCP - 1nos Focus Room : smoke sensor - 1nos Passion Room : smoke sensor - 1nos Persistance room : smoke sensor - 1nos Commitment room : smoke snesor - 1nos Compassion room : smoke sensor - 1nos Courage room : smoke sensor - 1nos Potential room : smoke sensor - 1nos Purpose room : smoke sensor - 1nos Harmony room : smoke sensor - 1nos *2nd Floor* Floor Lobby : smoke sensor - 2nos Library : smoke sensor - 1nos Stores : smoke sensor - 1nos Ultrasound : smoke sensor - 1nos Doctors Lounge : smoke sensor : 1nos Lounge Gate : MCP - 1nos Lounge Lobby : smoke sensor : 2nos Dream room : smoke sensor - 1nos Discipline room : smoke sensor - 1nos Hungry room : Gas Leak Detector - 1nos *3rd Floor* Vision Room : smoke sensor - 1nos Lobby : MCP - 1nos Open Terrace : AGNI SOUNDER RED : 1nos Open terrace : smoke sensor - 1nos Cssid room : smoke sensor - 1nos Papa Ji office : smoke sensor : 1nos Mandir : smoke sensor - 1nos Lift Room : smoke sensor - 1nos Staff room : smoke sensor - 1nos Not visited many Rooms because of doctors restrictions as there are many patients checking and some are admitted. Ony Checked : Ground Floor lobby , Sitting area , 1st floor lobby , 2nd floor lobby , library, lounge lobby, Hungry, 3rd floor vision, lobby, open terrace ,Mainly information provided by Womens hospital staff person Total Devices :- Smoke sensors : 36nos Ground floor - 8nos 1st floor - 11nos 2nd floor - 10nos 3rd floor - 7nos Sounder : 2nos MCP : 4nos Gas leak detector : 1nos (Hungry Room 2nd floor)</p>	
	09-02-2021 10:42:11	RishiDesai	New		-
	09-02-2021 10:41:53	RishiDesai	New		-

Previous Complain History :	Date Time	Technician Name	Remark
	03-08-2023 04:02:35	Ishwar Meena	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.
	15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.