

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9053																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9702786668																			
Technician Name :	Ishwar Meena		Technician Mobile :	9165341500																
Ticket Type :	Complain	Date & Time :	03-08-2023 04:02:35																	
Vendor Details :																				
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	9702786668	Name :	Nazia															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-09-2020 12:00:00		Type :	Comprehensive																
Product Name :	CCTV																			
Complain :	MRD Cabin 1 camera need to install with cabling																			
Technician Comment :	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-08-2023 04:06:26</td><td>Ishwar Meena</td><td>Completed</td><td>(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.</td><td></td></tr><tr><td>03-08-2023 04:03:20</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-08-2023 04:06:26	Ishwar Meena	Completed	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.		03-08-2023 04:03:20	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-08-2023 04:06:26	Ishwar Meena	Completed	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.																	
03-08-2023 04:03:20	Ishwar Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-07-2023 10:32:24</td><td>Atique Salmani</td><td>In Manju mam phone cctv online done working ok.</td></tr><tr><td>23-06-2023 10:31:29</td><td>Atique Salmani</td><td>All smok detector checked working ok also check by mcps and o.t. door access issue resolved 3rd floor 3 camera issue resolved and one smoke detector by pass by our engineer so it's need to fix in boss office in next visit boss meeting going on so painting.</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.	23-06-2023 10:31:29	Atique Salmani	All smok detector checked working ok also check by mcps and o.t. door access issue resolved 3rd floor 3 camera issue resolved and one smoke detector by pass by our engineer so it's need to fix in boss office in next visit boss meeting going on so painting.						
Date Time	Technician Name	Remark																		
15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.																		
23-06-2023 10:31:29	Atique Salmani	All smok detector checked working ok also check by mcps and o.t. door access issue resolved 3rd floor 3 camera issue resolved and one smoke detector by pass by our engineer so it's need to fix in boss office in next visit boss meeting going on so painting.																		