

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9468																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9702786668																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	08-09-2023 01:04:56																	
Vendor Details :																				
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	9702786668	Name :	Nazia															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-09-2020 12:00:00		Type :	Comprehensive																
Product Name :	Fire																			
Complain :	in pump room and one other location heat detector need to install with cabling survey need to do																			
Technician Comment :	2 heat detector 1 near coffee machine and 2 is in pump room cable approx 55/60 meter																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 heat detector 1 near coffee machine and 2 is in pump room cable approx 55/60 meter																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-09-2023 06:29:23</td><td>Atique Salmani</td><td>Completed</td><td>2 heat detector 1 near coffee machine and 2 is in pump room cable approx 55/60 meter</td><td></td></tr><tr><td>09-09-2023 11:46:17</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-09-2023 06:29:23	Atique Salmani	Completed	2 heat detector 1 near coffee machine and 2 is in pump room cable approx 55/60 meter		09-09-2023 11:46:17	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-09-2023 06:29:23	Atique Salmani	Completed	2 heat detector 1 near coffee machine and 2 is in pump room cable approx 55/60 meter																	
09-09-2023 11:46:17	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-08-2023 04:02:35</td><td>Ishwar Meena</td><td>(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.</td></tr><tr><td>15-07-2023 10:32:24</td><td>Atique Salmani</td><td>In Manju mam phone cctv online done working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-08-2023 04:02:35	Ishwar Meena	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.	15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.						
Date Time	Technician Name	Remark																		
03-08-2023 04:02:35	Ishwar Meena	(1) One IP Dome camera install. (2) 30 meter cat6 cable use. NVR cabin se mrd room Tak cable meter 00 - 30 mtr. (3) All camere working ok.																		
15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.																		