Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE4886								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9967522687							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965				
Ticket Type:	New Installation	Date & Time:	26-02-2022 03:10:10					
Vendor Details :								
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir			
Address:								
Mumbai , , , 400086 , Maharashtra								
AMC Details:								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain:	h wing - CCTV installation							
Technician Comment :	H wing total 16 camera install also and one camera install but client side one camera remove (Brijesh sir cabin) confirm to Bhavesh sir total 15 camera ok working done and angle set, and all recording going on in DVR password capital (L) F wing side two camera install and ok working done and h wing one camera install Fram rate bit rate 18/986 and two power supply hondover to Sunil sir and one power supply uesd. f wing for two camera							
Complain Operator :	Desktop - Apurva Vajaria							
Remark :	H wing total 16 camera install also and one camera install but client side one camera remove (Brijesh sir cabin) confirm to Bhavesh sir total 15 camera ok working done and angle set , and all recording going on in DVR password capital (L) F wing side two camera install and ok working done and h wing one camera install Fram rate bit rate 18/986 and two power supply hondover to Sunil sir and one power supply uesd. f wing for two camera							

Status History :	Date Time	Technician Name	Status	Remark	Sign	
	14-03-2022 06:17:00	Ravi Rajbhar	Completed	H wing total 16 camera install also and one camera install but client side one camera remove (Brijesh sir cabin) confirm to Bhavesh sir total 15 camera ok working done and angle set, and all recording going on in DVR password capital (L) F wing side two camera install and ok working done and h wing one camera install Fram rate bit rate 18/986 and two power supply hondover to Sunil sir and one power supply uesd. f wing for two camera	X\%'/	
	14-03-2022 10:10:23	Ravi Rajbhar	New		-	
	01-03-2022 10:42:15	Ravi Rajbhar	New		-	
	26-02-2022 03:10:24	Ravi Rajbhar	New		-	
	26-02-2022 03:10:10	Ravi Rajbhar	New		-	
Previous Complain	Date Time	Technician Name		Remark		
History:	08-03-2022 11:53:02	Ravi Rajbhar		sales office camera viewing ok off 3 TV usb extender handover to vishwash		
	05-03-2022 05:05:33	Siddhesh Chavan		6 camera no video issue resolved and power supply reconstruction and all camera working ok		