




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8254																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9967522687																			
Technician Name :	Ishwar Meena		Technician Mobile :	9165341500																
Ticket Type :	Complain	Date & Time :	03-05-2023 02:27:15																	
Vendor Details :																				
Company Name/Client Name :	Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir															
Address :																				
Mumbai , , , 400086 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	main gate camera recording issue																			
Technician Comment :	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-05-2023 05:43:06</td><td>Ishwar Meena</td><td>Completed</td><td>(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.</td><td></td></tr><tr><td>03-05-2023 02:27:23</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-05-2023 05:43:06	Ishwar Meena	Completed	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.		03-05-2023 02:27:23	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-05-2023 05:43:06	Ishwar Meena	Completed	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.																	
03-05-2023 02:27:23	Ishwar Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-05-2023 10:21:03</td><td>SantoshPathak</td><td></td></tr><tr><td>28-04-2023 03:19:29</td><td>Atique Salmani</td><td>16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-05-2023 10:21:03	SantoshPathak		28-04-2023 03:19:29	Atique Salmani	16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir						
Date Time	Technician Name	Remark																		
13-05-2023 10:21:03	SantoshPathak																			
28-04-2023 03:19:29	Atique Salmani	16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir																		