




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8544</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9967522687																								
<b>Technician Name :</b>	Sonu Kumar		<b>Technician Mobile :</b>	8454016444																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-06-2023 12:38:08																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Tivon Park G&H Wing	<b>Customer's Mobile :</b>	9967522687	<b>Name :</b>	Nilesh Sir																				
<b>Address :</b>																									
Mumbai , , , 400086 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	Need to give recording in pendrive																								
<b>Technician Comment :</b>	H wing recording seen by Rohit sir in video in mobile phone																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	H wing recording seen by Rohit sir in video in mobile phone																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2023 03:47:59</td><td>Sonu Kumar</td><td>Completed</td><td>H wing recording seen by Rohit sir in video in mobile phone</td><td></td></tr><tr><td>10-06-2023 02:33:04</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>10-06-2023 12:38:16</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2023 03:47:59	Sonu Kumar	Completed	H wing recording seen by Rohit sir in video in mobile phone		10-06-2023 02:33:04	Sonu Kumar	New		-	10-06-2023 12:38:16	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-06-2023 03:47:59	Sonu Kumar	Completed	H wing recording seen by Rohit sir in video in mobile phone																						
10-06-2023 02:33:04	Sonu Kumar	New		-																					
10-06-2023 12:38:16	Sonu Kumar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-06-2023 10:19:44</td><td>Kalpesh SubhashGurav</td><td>G 602 Line OK Telephone Faulty</td></tr><tr><td>31-05-2023 03:49:45</td><td>Kalpesh SubhashGurav</td><td>VDP Power supply Installed Done. VDP Working.</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-06-2023 10:19:44	Kalpesh SubhashGurav	G 602 Line OK Telephone Faulty	31-05-2023 03:49:45	Kalpesh SubhashGurav	VDP Power supply Installed Done. VDP Working.											
Date Time	Technician Name	Remark																							
17-06-2023 10:19:44	Kalpesh SubhashGurav	G 602 Line OK Telephone Faulty																							
31-05-2023 03:49:45	Kalpesh SubhashGurav	VDP Power supply Installed Done. VDP Working.																							