







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3728																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9004700906																																		
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																															
Ticket Type :	Call Basis	Date & Time :	30-08-2021 11:08:38																																
Vendor Details :																																			
Company Name/Client Name :	Value Beverage	Customer's Mobile :	9004700906	Name :	Poonam Madam																														
Address :																																			
Mumbai , , , 400710 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Access																																		
Complain :	Lock issue																																		
Technician Comment :	1 look nuw install done and 12 Miter cebel done																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	1 look nuw install done and 12 Miter cebel done																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-08-2021 05:55:54</td><td>Shiva Meena</td><td>Completed</td><td>1 look nuw install done and 12 Miter cebel done</td><td></td></tr><tr><td>31-08-2021 10:58:09</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>30-08-2021 08:59:53</td><td>Shiva Meena</td><td>Work Pending</td><td>lock bolt change and 1 lock cabing issues and 2 door alignment issues lock scroow looss work pending</td><td></td></tr><tr><td>30-08-2021 11:08:54</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>30-08-2021 11:08:39</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-08-2021 05:55:54	Shiva Meena	Completed	1 look nuw install done and 12 Miter cebel done		31-08-2021 10:58:09	Shiva Meena	New		-	30-08-2021 08:59:53	Shiva Meena	Work Pending	lock bolt change and 1 lock cabing issues and 2 door alignment issues lock scroow looss work pending		30-08-2021 11:08:54	Shiva Meena	New		-	30-08-2021 11:08:39	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																															
31-08-2021 05:55:54	Shiva Meena	Completed	1 look nuw install done and 12 Miter cebel done																																
31-08-2021 10:58:09	Shiva Meena	New		-																															
30-08-2021 08:59:53	Shiva Meena	Work Pending	lock bolt change and 1 lock cabing issues and 2 door alignment issues lock scroow looss work pending																																
30-08-2021 11:08:54	Shiva Meena	New		-																															
30-08-2021 11:08:39	Shiva Meena	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2023 10:28:43</td><td>Atique Salmani</td><td>Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock allingment done and magnet fixed proper . Also checked production room door lock .</td></tr><tr><td>13-06-2023 10:53:23</td><td>MayurYadav</td><td>Ground floor Access door push button cable one pair not working Pair change door working ok open with push button</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2023 10:28:43	Atique Salmani	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock allingment done and magnet fixed proper . Also checked production room door lock .	13-06-2023 10:53:23	MayurYadav	Ground floor Access door push button cable one pair not working Pair change door working ok open with push button																					
Date Time	Technician Name	Remark																																	
10-07-2023 10:28:43	Atique Salmani	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock allingment done and magnet fixed proper . Also checked production room door lock .																																	
13-06-2023 10:53:23	MayurYadav	Ground floor Access door push button cable one pair not working Pair change door working ok open with push button																																	

