




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE78																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9619151939																			
Technician Name :	Sachin Pawar		Technician Mobile :	8080922981																
Ticket Type :	Complain	Date & Time :	17-08-2019 11:03:15																	
Vendor Details :																				
Company Name/Client Name :	Taj Hotel Santacruz	Customer's Mobile :	9619151939	Name :	Purnanand Petwal															
Address :																				
Mumbai , Santacruz East, Mumbai, Maharashtra, India , , 400099 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Alarm System																			
Complain :	Visit for rooms available																			
Technician Comment :	1 check mention rooms:548 , 643, 333, 336, 338, 347, 2 643 mc sensor and magnet is installed. new frame is fitted from carpenter in the same room.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1 check mention rooms:548 , 643, 333, 336, 338, 347, 2 643 mc sensor and magnet is installed. new frame is fitted from carpenter in the same room.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-08-2019 04:47:11</td><td>SachinPawar</td><td>Completed</td><td>1 check mention rooms:548 , 643, 333, 336, 338, 347, 2 643 mc sensor and magnet is installed. new frame is fitted from carpenter in the same room.</td><td></td></tr><tr><td>17-08-2019 11:03:18</td><td>SachinPawar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-08-2019 04:47:11	SachinPawar	Completed	1 check mention rooms:548 , 643, 333, 336, 338, 347, 2 643 mc sensor and magnet is installed. new frame is fitted from carpenter in the same room.		17-08-2019 11:03:18	SachinPawar	New		-
Date Time	Technician Name	Status	Remark	Sign																
17-08-2019 04:47:11	SachinPawar	Completed	1 check mention rooms:548 , 643, 333, 336, 338, 347, 2 643 mc sensor and magnet is installed. new frame is fitted from carpenter in the same room.																	
17-08-2019 11:03:18	SachinPawar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-06-2023 11:07:42</td><td>Ravi Rajbhar</td><td>437 need to change small cricit with magnetic contact 446 issue resloved 445 issue resloved</td></tr><tr><td>22-08-2022 01:13:19</td><td>Prashant Nikalje</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	13-06-2023 11:07:42	Ravi Rajbhar	437 need to change small cricit with magnetic contact 446 issue resloved 445 issue resloved	22-08-2022 01:13:19	Prashant Nikalje							
Date Time	Technician Name	Remark																		
13-06-2023 11:07:42	Ravi Rajbhar	437 need to change small cricit with magnetic contact 446 issue resloved 445 issue resloved																		
22-08-2022 01:13:19	Prashant Nikalje																			