## **Vallabh Enterprises**

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE8009							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9967718539						
Technician Name :	Sonu Kumar		Technician:	Technician Mobile :		8454016444	
Ticket Type :	Complain	Date & Time :	31-03-2023 04:38:20				
Vendor Details :							
Company Name/Client Name :	SSL Aurangabad	Customer's Mobile:	e 9967718539		Name:	Raees Sir	
Address :							
Mumbai,,,,Maharashtra							
AMC Details:							
Expiry Date :	01-01-1970 05:30:00	Type:					
<b>Product Name:</b>	CCTV						
Complain:	2 camera shift need to do						
Technician Comment :	2camera shifting done 1 camera ground floor and 1 camera 1st floor						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	2camera shifting done 1 camera ground floor and 1 camera 1st floor						
<b>Status History:</b>	Date Time	Technician Nam	e Status	Remark		Sign	
	31-03-2023 05:47:35	Sonu Kumar	Completed	2camera shifting done 1 camera ground floor and 1 camera 1st floor		· /	
	31-03-2023 04:38:44	Sonu Kumar	New			-	
Previous Complain	Date Time	Technician Name	Remark				
History:	03-03-2023 10:10:57	Sonu Kumar					
	11-01-2023 12:13:14	Ravi Rajbhar	Fist floor and ground floor fire exit door push bar installation done and ok working Two magnetic contacts ,two hooter two single push bar , with two power supply install with cable				