

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12233																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833008982																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	24-07-2024 06:06:16																	
Vendor Details :																				
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	9833008982	Name :	Rajan Bhai															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	flat no. 111A/81 - intercom not working																			
Technician Comment :	92 issue resolved 81 cable +instrument A 111 line ok instrument . Entry gate instrument need to changed . Display time reset . All floor cable mash need to clear and required crone n junction box																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	92 issue resolved 81 cable +instrument A 111 line ok instrument . Entry gate instrument need to changed . Display time reset . All floor cable mash need to clear and required crone n junction box																			
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>26-07-2024 05:44:45</td><td>Atique Salmani</td><td>Completed</td><td>92 issue resolved 81 cable +instrument A 111 line ok instrument . Entry gate instrument need to changed . Display time reset . All floor cable mash need to clear and required crone n junction box</td><td></td></tr><tr><td>25-07-2024 04:52:40</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	26-07-2024 05:44:45	Atique Salmani	Completed	92 issue resolved 81 cable +instrument A 111 line ok instrument . Entry gate instrument need to changed . Display time reset . All floor cable mash need to clear and required crone n junction box		25-07-2024 04:52:40	Atique Salmani	New		-
	Date Time	Technician Name	Status	Remark	Sign															
	26-07-2024 05:44:45	Atique Salmani	Completed	92 issue resolved 81 cable +instrument A 111 line ok instrument . Entry gate instrument need to changed . Display time reset . All floor cable mash need to clear and required crone n junction box																
25-07-2024 04:52:40	Atique Salmani	New		-																
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>23-07-2024 12:04:57</td><td>Shiva Meena</td><td>18 floor 182 not find cebal 63 cebal ok and phone ok 172 ceblig ok phone ok</td></tr><tr><td>16-07-2024 02:27:33</td><td>Sonu Kumar</td><td>Flat no 801 cable faulty cable need to change</td></tr></table>					Date Time	Technician Name	Remark	23-07-2024 12:04:57	Shiva Meena	18 floor 182 not find cebal 63 cebal ok and phone ok 172 ceblig ok phone ok	16-07-2024 02:27:33	Sonu Kumar	Flat no 801 cable faulty cable need to change						
	Date Time	Technician Name	Remark																	
	23-07-2024 12:04:57	Shiva Meena	18 floor 182 not find cebal 63 cebal ok and phone ok 172 ceblig ok phone ok																	
16-07-2024 02:27:33	Sonu Kumar	Flat no 801 cable faulty cable need to change																		