

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12330																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9833008982																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	03-08-2024 11:09:28																						
Vendor Details :																									
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	9833008982	Name :	Rajan Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	backside gate cabin new phone need to send and flat no. 91 intercom issue																								
Technician Comment :	back side gate new instrument install and ok working done and flat no. 91 intercom all ready ok working done																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	back side gate new instrument install and ok working done and flat no. 91 intercom all ready ok working done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-08-2024 02:44:58</td><td>Ravi Rajbhar</td><td>Completed</td><td>back side gate new instrument install and ok working done and flat no. 91 intercom all ready ok working done</td><td></td></tr><tr><td>05-08-2024 09:57:40</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>03-08-2024 05:58:41</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-08-2024 02:44:58	Ravi Rajbhar	Completed	back side gate new instrument install and ok working done and flat no. 91 intercom all ready ok working done		05-08-2024 09:57:40	Ravi Rajbhar	New		-	03-08-2024 05:58:41	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-08-2024 02:44:58	Ravi Rajbhar	Completed	back side gate new instrument install and ok working done and flat no. 91 intercom all ready ok working done																						
05-08-2024 09:57:40	Ravi Rajbhar	New		-																					
03-08-2024 05:58:41	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-08-2024 12:10:02</td><td>Ravi Rajbhar</td><td>flat no.152 intercom issue resolved and ok working done</td></tr><tr><td>17-08-2024 11:19:50</td><td>Ravi Rajbhar</td><td>flat no.93 intercom issue resolved and ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-08-2024 12:10:02	Ravi Rajbhar	flat no.152 intercom issue resolved and ok working done	17-08-2024 11:19:50	Ravi Rajbhar	flat no.93 intercom issue resolved and ok working done											
Date Time	Technician Name	Remark																							
17-08-2024 12:10:02	Ravi Rajbhar	flat no.152 intercom issue resolved and ok working done																							
17-08-2024 11:19:50	Ravi Rajbhar	flat no.93 intercom issue resolved and ok working done																							