




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1934</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8169144587																								
<b>Technician Name :</b>	Neeraj Chauhan		<b>Technician Mobile :</b>	8898885764																					
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	01-10-2020 05:34:54																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir																				
<b>Address :</b>																									
Mumbai , , , 400076 , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Access																								
<b>Complain :</b>	Installation of access Control system																								
<b>Technician Comment :</b>	3 Em lock install /3 sf hundred install 23 meater cabling done all installed material install removed all materiyal handover by seurty person																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	3 Em lock install /3 sf hundred install 23 meater cabling done all installed material install removed all materiyal handover by seurty person																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2020 10:24:51</td><td>Neeraj Chauhan</td><td>Completed</td><td>3 Em lock install /3 sf hundred install 23 meater cabling done all installed material install removed all materiyal handover by seurty person</td><td></td></tr><tr><td>22-10-2020 10:57:42</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2020 05:34:54</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2020 10:24:51	Neeraj Chauhan	Completed	3 Em lock install /3 sf hundred install 23 meater cabling done all installed material install removed all materiyal handover by seurty person		22-10-2020 10:57:42	Neeraj Chauhan	New		-	01-10-2020 05:34:54	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-10-2020 10:24:51	Neeraj Chauhan	Completed	3 Em lock install /3 sf hundred install 23 meater cabling done all installed material install removed all materiyal handover by seurty person																						
22-10-2020 10:57:42	Neeraj Chauhan	New		-																					
01-10-2020 05:34:54	Neeraj Chauhan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.											
Date Time	Technician Name	Remark																							
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																							
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																							