Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiabnsecure@yanoo.co.in							
Service Status Details : VE3287							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169144587						
Technician Name :	Siddhesh Chavan		Technician Mobile 808092298				
Ticket Type :	New Installation	Date & Time :	23-06-2021 10:24:00				
Vendor Details :							
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587		Name :	Rajendra Sir	
Address:							
Mumbai , , , 4000'	76 , Maharashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:0	0	Type:	Type:			
Product Name:	CCTV						
Complain :	install DVR						
Technician Comment :	install new 16 chanel dvr and 10 camera started and all satting and one camera no video issue resolved and one camera angle satting done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	install new 16 chanel dvr and 10 camera started and all satting and one camera no video issue resolved and one camera angle satting done						
Status History:	Date Time	Technician Name	Status	Remark		Sign	
	23-06-2021 02:47:07	Siddhesh Chavan	Completed	and 10 c all sattin no video	install new 16 chanel dvr and 10 camera started and all satting and one camera no video issue resolved and one camera angle satting done		
	23-06-2021 10:24:39	Siddhesh Chavan	New			-	
	23-06-2021 10:24:00	Siddhesh Chavan	New			-	
Previous Complain	Date Time	Technician Name	Remark				
History:	27-07-2023 03:28:07	Kalpesh SubhashGurav	port issue Li technician D Required Lol	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required			
	16-05-2023 09:57:14	Atique Salmani	coverd by 25	Ther is wire cut by mouse so rejoint 8 core wire and also coverd by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.			