

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE377																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8169144587																								
Technician Name :	Mahindra Prajapati		Technician Mobile :	7678020599																					
Ticket Type :	Complain	Date & Time :	19-09-2019 12:16:01																						
Vendor Details :																									
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir																				
Address :																									
Mumbai , , , 400076 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	install 2-3 cameras date time issue check lift cabling done or not																								
Technician Comment :	11 camera installation and angal sating and 3 camera wiring.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	11 camera installation and angal sating and 3 camera wiring.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-09-2019 09:50:02</td><td>MahindraPrajapati</td><td>Completed</td><td>11 camera installation and angal sating and 3 camera wiring.</td><td></td></tr><tr><td>19-09-2019 12:16:08</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr><tr><td>19-09-2019 12:16:01</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-09-2019 09:50:02	MahindraPrajapati	Completed	11 camera installation and angal sating and 3 camera wiring.		19-09-2019 12:16:08	MahindraPrajapati	New		-	19-09-2019 12:16:01	MahindraPrajapati	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-09-2019 09:50:02	MahindraPrajapati	Completed	11 camera installation and angal sating and 3 camera wiring.																						
19-09-2019 12:16:08	MahindraPrajapati	New		-																					
19-09-2019 12:16:01	MahindraPrajapati	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.											
Date Time	Technician Name	Remark																							
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																							
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																							