## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE10805		
Created By:         Admin - Apurva Vajaria           Complaint Mob. No.:         8369082393           Technician Name:         Alique Salmani           Technician Mobile:         8080922984           Ticket Type:         Complain         Date & Time:         13-02-2024 01:15-36		
Complaint Mob. No.:         8369082393           Technician Name:         Atique Salmani         Technician Mobile:         8080922984           Ticket Type:         Complain         Date & Time:         13-02-2024 01:15:36         8080922984		
No. :         Technician Name :         Atique Salmani         Technician Mobile :         8080922984           Ticket Type :         Complain         Date & Time :         13-02-2024 01:15:36         8080922984		
Ticket Type :         Complain         Date & Time :         13-02-2024 01:15:36		
Vendor Details:		
Vendor Details :		
Company Mahavir Bliss Thane(shiv Shakti) Customer's Mohile : 8369082393 Name : Rajesh Sir	,	
Address:		
Mumbai, , , , Maharashtra		
AMC Details:		
Expiry Date : 01-01-1970 05:30-00 Type :		
Product Name: CCTV		
Complain: Sidhesh visited, he asked the client to install some cables frm 1 camera to the DVR end & there was an armored cable in the client's pass in spare. Siddesh check and said it was ok He got that cable instal but now when Sonu visited said c	ble is faulty	
Technician Comment:  One camera back side check the cable continuity and used vedeo cable with shield working ok And main gate 2 cameras reconnection working ok total 3 cameras issue resolved.		
Complain Operator : Desktop - Apurva Vajaria :		
Remark: One camera back side check the cable continuity and used vedeo cable with shield working ok And main gate 2 cameras reconnection working ok total 3 cameras issue resolved.		

Ship the shi Smit Smit Smit Smit Simp Smit Smit Smy Smit Smit Smile Smit SIF Smit Smit Smit SINF Smit SMF SINT Smit SINT SMF Smy SMF SMF SINT

 
 Previous Complain History:
 Date Time
 Technician Name
 Remark

 0.02 2023 02 18.39
 Some Kumar
 1 new camera installation done main gate and back talled 1 camera angle setting done 1 line and dic used