







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15282																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820007487																								
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																					
Ticket Type :	Complain	Date & Time :	16-07-2025 10:23:44																						
Vendor Details :																									
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	B wing lift 1 camera off issue																								
Technician Comment :	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-07-2025 12:39:11</td><td>Neeraj Chauhan</td><td>Completed</td><td>B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk</td><td></td></tr><tr><td>16-07-2025 12:39:11</td><td>Neeraj Chauhan</td><td>Completed</td><td>B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk</td><td></td></tr><tr><td>16-07-2025 10:24:21</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-07-2025 12:39:11	Neeraj Chauhan	Completed	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk		16-07-2025 12:39:11	Neeraj Chauhan	Completed	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk		16-07-2025 10:24:21	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-07-2025 12:39:11	Neeraj Chauhan	Completed	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk																						
16-07-2025 12:39:11	Neeraj Chauhan	Completed	B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk																						
16-07-2025 10:24:21	Neeraj Chauhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-07-2025 10:31:03</td><td>PravinJagade</td><td>A wing passage camera off issue resolved done. Work complete.</td></tr><tr><td>26-06-2025 10:03:16</td><td>Siddhesh Chavan</td><td>F wing watchman intercom issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-07-2025 10:31:03	PravinJagade	A wing passage camera off issue resolved done. Work complete.	26-06-2025 10:03:16	Siddhesh Chavan	F wing watchman intercom issue resolved											
Date Time	Technician Name	Remark																							
03-07-2025 10:31:03	PravinJagade	A wing passage camera off issue resolved done. Work complete.																							
26-06-2025 10:03:16	Siddhesh Chavan	F wing watchman intercom issue resolved																							