

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4877					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9820007487				
Technician Name :	Atique Salmani		Technician Mobile :	8080922984	
Ticket Type :	Complain	Date & Time :	25-02-2022 03:27:18		
Vendor Details :					
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Intercom				
Complain :	f wing intercom need to check				
Technician Comment :	402 instrument not available line ok 302 not working so repunchin from system working ok. 202 out of country 203 only check working ok. 204 RJ 11 port use another port and reconnection from duct working ok. 1301 flate to duct cable faulty 1104 door lock out of country 1004.instrument not available also not interested. 904.door lock 601.line ok instrument not available. 692 .door lock 603 .tested ok .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	402 instrument not available line ok 302 not working so repunchin from system working ok. 202 out of country 203 only check working ok. 204 RJ 11 port use another port and reconnection from duct working ok. 1301 flate to duct cable faulty 1104 door lock out of country 1004.instrument not available also not interested. 904.door lock 601.line ok instrument not available. 692 .door lock 603 .tested ok .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	25-02-2022 05:18:05	Atique Salmani	Completed	402 instrument not available line ok 302 not working so repunchin from system working ok. 202 out of country 203 only check working ok. 204 RJ 11 port use another port and reconnection from duct working ok. 1301 flate to duct cable faulty 1104 door lock out of country 1004.instrument not available also not interested. 904.door lock 601.line ok instrument not available. 692 .door lock 603 .tested ok .	
	25-02-2022 03:27:42	Atique Salmani	New		-
	25-02-2022 03:27:18	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	25-02-2022 03:26:07	Atique Salmani	a wing passage camera give sarate 24*7 230 for camera adapter working ok.		
	22-02-2022 10:29:38	Siddhesh Chavan	ppm done and 2 camera video issue pending and and f wing backside camera video issue pending		