




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7132																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9869439970																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	19-12-2022 11:31:29																	
Vendor Details :																				
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	camera no 14 need to check																			
Technician Comment :	Camera nmbr 14 near calss shop side need to shift with 3 ft pole by fabricator bcoz light is on focus to camera lence so need to shift .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Camera nmbr 14 near calss shop side need to shift with 3 ft pole by fabricator bcoz light is on focus to camera lence so need to shift .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-12-2022 06:40:22</td><td>Atique Salmani</td><td>Client Side</td><td>Camera nmbr 14 near calss shop side need to shift with 3 ft pole by fabricator bcoz light is on focus to camera lence so need to shift .</td><td></td></tr><tr><td>19-12-2022 11:31:40</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-12-2022 06:40:22	Atique Salmani	Client Side	Camera nmbr 14 near calss shop side need to shift with 3 ft pole by fabricator bcoz light is on focus to camera lence so need to shift .		19-12-2022 11:31:40	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
19-12-2022 06:40:22	Atique Salmani	Client Side	Camera nmbr 14 near calss shop side need to shift with 3 ft pole by fabricator bcoz light is on focus to camera lence so need to shift .																	
19-12-2022 11:31:40	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 10:11:24</td><td>Ravi Rajbhar</td><td>cctv systam check recoding going on in nvr or dvr proper workong done</td></tr><tr><td>25-07-2023 11:47:47</td><td>Atique Salmani</td><td>Camera nmbr 16 is lift camera BNC changed working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 10:11:24	Ravi Rajbhar	cctv systam check recoding going on in nvr or dvr proper workong done	25-07-2023 11:47:47	Atique Salmani	Camera nmbr 16 is lift camera BNC changed working ok						
Date Time	Technician Name	Remark																		
27-07-2023 10:11:24	Ravi Rajbhar	cctv systam check recoding going on in nvr or dvr proper workong done																		
25-07-2023 11:47:47	Atique Salmani	Camera nmbr 16 is lift camera BNC changed working ok																		