

B K Infotech

Regd. Office : B K InfoTech Basement No 003, Dattani Trade Center Near BMC Office Chandavarkar Road, Borivali West Mumbai - 92
Support : | **W :** <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1433																														
Priority :	High																													
Created By :	Admin - Kalpesh Jain																													
Complaint Mob. No. :	9820972760																													
Technician Name :	Javed Uddin		Technician Mobile :	8601226063																										
Ticket Type :	Complain	Date & Time :	26-12-2019 10:45:53																											
Vendor Details :																														
Company Name/Client Name :	Sadguru Engineering Works	Customer's Mobile :	9820972760	Name :	Rajesh																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	camera service cctv																													
Complain :	camera issue																													
Technician Comment :	24 mate 4+1 wir and 3 connectors installation Done (actual measurement of 16 mts)																													
Complain Operator :	Desktop - Kalpesh Jain																													
Remark :	24 mate 4+1 wir and 3 connectors installation Done (actual measurement of 16 mts)																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-12-2019 01:09:37</td><td>JavedUddin</td><td>Completed</td><td>24 mate 4+1 wir and 3 connectors installation Done (actual measurement of 16 mts)</td><td></td></tr><tr><td>26-12-2019 01:54:59</td><td>JavedUddin</td><td>Work Pending</td><td>wire installation and (one camera installation if required)</td><td></td></tr><tr><td>26-12-2019 10:46:01</td><td>JavedUddin</td><td>New</td><td></td><td>-</td></tr><tr><td>26-12-2019 10:45:54</td><td>JavedUddin</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-12-2019 01:09:37	JavedUddin	Completed	24 mate 4+1 wir and 3 connectors installation Done (actual measurement of 16 mts)		26-12-2019 01:54:59	JavedUddin	Work Pending	wire installation and (one camera installation if required)		26-12-2019 10:46:01	JavedUddin	New		-	26-12-2019 10:45:54	JavedUddin	New		-
Date Time	Technician Name	Status	Remark	Sign																										
27-12-2019 01:09:37	JavedUddin	Completed	24 mate 4+1 wir and 3 connectors installation Done (actual measurement of 16 mts)																											
26-12-2019 01:54:59	JavedUddin	Work Pending	wire installation and (one camera installation if required)																											
26-12-2019 10:46:01	JavedUddin	New		-																										
26-12-2019 10:45:54	JavedUddin	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-11-2019 01:24:51</td><td>Manish Dhangar</td><td>1 cpluse power supply install</td></tr><tr><td>09-09-2019 12:15:29</td><td>Manish Dhangar</td><td>3. dome camera install hikvision 3.6mm 6. BNC connector 3 DC pin 135 . mitre 4+1 wire install service charge ???</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-11-2019 01:24:51	Manish Dhangar	1 cpluse power supply install	09-09-2019 12:15:29	Manish Dhangar	3. dome camera install hikvision 3.6mm 6. BNC connector 3 DC pin 135 . mitre 4+1 wire install service charge ???																
Date Time	Technician Name	Remark																												
30-11-2019 01:24:51	Manish Dhangar	1 cpluse power supply install																												
09-09-2019 12:15:29	Manish Dhangar	3. dome camera install hikvision 3.6mm 6. BNC connector 3 DC pin 135 . mitre 4+1 wire install service charge ???																												