




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3214</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820842494																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	09-06-2021 09:56:47																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Bombay Dyeing Worli	Customer's Mobile :	9820842494	Name :	Rajiv Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	one camera issue																								
<b>Technician Comment :</b>	two camera power supply Check and also ok working infrom to ready sir and electrician and 2 camera pinkes issue back gate exit																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	two camera power supply Check and also ok working infrom to ready sir and electrician and 2 camera pinkes issue back gate exit																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-06-2021 11:11:30</td><td>Ravi Rajbhar</td><td>Completed</td><td>two camera power supply Check and also ok working infrom to ready sir and electrician and 2 camera pinkes issue back gate exit</td><td></td></tr><tr><td>09-06-2021 09:56:59</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>09-06-2021 09:56:47</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-06-2021 11:11:30	Ravi Rajbhar	Completed	two camera power supply Check and also ok working infrom to ready sir and electrician and 2 camera pinkes issue back gate exit		09-06-2021 09:56:59	Ravi Rajbhar	New		-	09-06-2021 09:56:47	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
09-06-2021 11:11:30	Ravi Rajbhar	Completed	two camera power supply Check and also ok working infrom to ready sir and electrician and 2 camera pinkes issue back gate exit																						
09-06-2021 09:56:59	Ravi Rajbhar	New		-																					
09-06-2021 09:56:47	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 03:30:10</td><td>DilshadKhan</td><td></td></tr><tr><td>26-07-2023 02:32:04</td><td>Ishwar Meena</td><td>New IP System camera dismental work done. All materials 1 NVR (Maltivision ) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 03:30:10	DilshadKhan		26-07-2023 02:32:04	Ishwar Meena	New IP System camera dismental work done. All materials 1 NVR (Maltivision ) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.											
Date Time	Technician Name	Remark																							
29-07-2023 03:30:10	DilshadKhan																								
26-07-2023 02:32:04	Ishwar Meena	New IP System camera dismental work done. All materials 1 NVR (Maltivision ) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.																							