




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4883																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820842494																								
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																					
Ticket Type :	Complain	Date & Time :	26-02-2022 12:26:34																						
Vendor Details :																									
Company Name/Client Name :	Rashmi Drashtant Bldg B And D	Customer's Mobile :	9820842494	Name :	Rajiv Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	1 camera survey																								
Technician Comment :	d wing side 55 to 60 MTR cabling with piping and watchman cabin 55 to 60 MTR cabling with piping and new dvr 4 channel one supply BNC dc hdd required by client																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	d wing side 55 to 60 MTR cabling with piping and watchman cabin 55 to 60 MTR cabling with piping and new dvr 4 channel one supply BNC dc hdd required by client																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-02-2022 01:08:48</td><td>Siddhesh Chavan</td><td>Completed</td><td>d wing side 55 to 60 MTR cabling with piping and watchman cabin 55 to 60 MTR cabling with piping and new dvr 4 channel one supply BNC dc hdd required by client</td><td></td></tr><tr><td>26-02-2022 12:26:47</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>26-02-2022 12:26:34</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-02-2022 01:08:48	Siddhesh Chavan	Completed	d wing side 55 to 60 MTR cabling with piping and watchman cabin 55 to 60 MTR cabling with piping and new dvr 4 channel one supply BNC dc hdd required by client		26-02-2022 12:26:47	Siddhesh Chavan	New		-	26-02-2022 12:26:34	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-02-2022 01:08:48	Siddhesh Chavan	Completed	d wing side 55 to 60 MTR cabling with piping and watchman cabin 55 to 60 MTR cabling with piping and new dvr 4 channel one supply BNC dc hdd required by client																						
26-02-2022 12:26:47	Siddhesh Chavan	New		-																					
26-02-2022 12:26:34	Siddhesh Chavan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-02-2022 12:14:06</td><td>YogeshDesai</td><td>New 2tb hd installed faulty hd given to client . all camera working ok all showing recording symbol . also shown to client . work completed.</td></tr><tr><td>14-01-2022 10:14:13</td><td>Siddhesh Chavan</td><td>one camera video issue resolved and all camera working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-02-2022 12:14:06	YogeshDesai	New 2tb hd installed faulty hd given to client . all camera working ok all showing recording symbol . also shown to client . work completed.	14-01-2022 10:14:13	Siddhesh Chavan	one camera video issue resolved and all camera working ok											
Date Time	Technician Name	Remark																							
08-02-2022 12:14:06	YogeshDesai	New 2tb hd installed faulty hd given to client . all camera working ok all showing recording symbol . also shown to client . work completed.																							
14-01-2022 10:14:13	Siddhesh Chavan	one camera video issue resolved and all camera working ok																							