




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8653																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820842494																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	AMC visiting	Date & Time :	24-06-2023 10:32:06																	
Vendor Details :																				
Company Name/Client Name :	Bombay Dyeing Worli	Customer's Mobile :	9820842494	Name :	Rajiv Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																
Product Name :	Ppm																			
Complain :	need to do cctv ppm																			
Technician Comment :	3dvr and 1 NVR pm done 3 camera off issue resolved working ok 2nd floor reception and vip lift entry and 2nd floor near server room																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	3dvr and 1 NVR pm done 3 camera off issue resolved working ok 2nd floor reception and vip lift entry and 2nd floor near server room																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-06-2023 02:47:06</td><td>Sonu Kumar</td><td>Completed</td><td>3dvr and 1 NVR pm done 3 camera off issue resolved working ok 2nd floor reception and vip lift entry and 2nd floor near server room</td><td></td></tr><tr><td>24-06-2023 10:32:23</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-06-2023 02:47:06	Sonu Kumar	Completed	3dvr and 1 NVR pm done 3 camera off issue resolved working ok 2nd floor reception and vip lift entry and 2nd floor near server room		24-06-2023 10:32:23	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-06-2023 02:47:06	Sonu Kumar	Completed	3dvr and 1 NVR pm done 3 camera off issue resolved working ok 2nd floor reception and vip lift entry and 2nd floor near server room																	
24-06-2023 10:32:23	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 03:30:10</td><td>DilshadKhan</td><td></td></tr><tr><td>26-07-2023 02:32:04</td><td>Ishwar Meena</td><td>New IP System camera dismental work done. All materials 1 NVR (Maltivision) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 03:30:10	DilshadKhan		26-07-2023 02:32:04	Ishwar Meena	New IP System camera dismental work done. All materials 1 NVR (Maltivision) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.						
Date Time	Technician Name	Remark																		
29-07-2023 03:30:10	DilshadKhan																			
26-07-2023 02:32:04	Ishwar Meena	New IP System camera dismental work done. All materials 1 NVR (Maltivision) 2 POE switch 8 IP Maltivision camera 8 IPC connector 7 camera ki cat6 cable 1 2U rack 1 VGA cable 1 Mause Handover to client.																		