







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13608																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8879611832																													
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																										
Ticket Type :	Complain	Date & Time :	21-12-2024 11:13:40																											
Vendor Details :																														
Company Name/Client Name :	Ornate Solitaire Dahisar	Customer's Mobile :	8879611832	Name :	Rauf Sir																									
Address :																														
Mumbai , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	office backside repaired camera need to install and some cable of crane was removed when we installed transmitter receiver... So need to check the qty																													
Technician Comment :	Back gate camera cable issue need to change in 55 to 60 MTR																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Back gate camera cable issue need to change in 55 to 60 MTR																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-12-2024 02:01:25</td><td>Sonu Kumar</td><td>Work Pending</td><td>Back gate camera cable issue need to change in 55 to 60 MTR</td><td></td></tr><tr><td>23-12-2024 10:23:49</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>21-12-2024 06:00:46</td><td>Sonu Kumar</td><td>Work Pending</td><td>Backside camera install and back gate camera off need to chek</td><td></td></tr><tr><td>21-12-2024 11:13:58</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-12-2024 02:01:25	Sonu Kumar	Work Pending	Back gate camera cable issue need to change in 55 to 60 MTR		23-12-2024 10:23:49	Sonu Kumar	New		-	21-12-2024 06:00:46	Sonu Kumar	Work Pending	Backside camera install and back gate camera off need to chek		21-12-2024 11:13:58	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
23-12-2024 02:01:25	Sonu Kumar	Work Pending	Back gate camera cable issue need to change in 55 to 60 MTR																											
23-12-2024 10:23:49	Sonu Kumar	New		-																										
21-12-2024 06:00:46	Sonu Kumar	Work Pending	Backside camera install and back gate camera off need to chek																											
21-12-2024 11:13:58	Sonu Kumar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-01-2025 04:58:10</td><td>Shiva Meena</td><td>Camera working and cebling work completed 131 Miter</td></tr><tr><td>10-01-2025 06:10:10</td><td>Shiva Meena</td><td>Cren camera work pending</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-01-2025 04:58:10	Shiva Meena	Camera working and cebling work completed 131 Miter	10-01-2025 06:10:10	Shiva Meena	Cren camera work pending																
Date Time	Technician Name	Remark																												
20-01-2025 04:58:10	Shiva Meena	Camera working and cebling work completed 131 Miter																												
10-01-2025 06:10:10	Shiva Meena	Cren camera work pending																												