Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE16045							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	8879611832							
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764				
Ticket Type :	Call Basis	Date & Time :	17-10-2025 12:38:58					
Vendor Details :								
Company Name/Client Name :	Ornate Solitaire Dahisar	Customer's Mobile :	8879611832	Name :	Rauf Sir			
Address:				-	-			
Mumbai , , , , Ma	harashtra							
AMC Details :	_							
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain :	All system off issue and 1 new camera at 1st floor new need to install - Pooja madam - 7977812170 - 750/- visiting charges							
Technician Comment :	1 bullet camera installation done camera okk							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	1 bullet camera installation done camera okk							

Status History :	Date Time	Technician Name		Status	Remark	Sign	
	10-11-2025 04:15:50	Neeraj Chauhan	Со	mpleted	1 bullet camera installation done camera okk	444	
	10-11-2025 04:08:04	Neeraj Chauhan	Ne	W		-	
	18-10-2025 11:30:04	Neeraj Chauhan		vaiting ares	Remooved from client side crane cameras device plug New software installation done in pc and 1 bullet camera collect and carane cameras 2 nos off due to remooved plug point now only 4 cameras working out of 7 also collect gpay 750	ris	
	18-10-2025 11:30:04	Neeraj Chauhan			Remooved from client side crane cameras device plug New software installation done in pc and 1 bullet camera collect and carane cameras 2 nos off due to remooved plug point now only 4 cameras working out of 7 also collect gpay 750	ris	
	17-10-2025 12:39:09	Neeraj Chauhan	New			-	
Previous Complain History :	Date Time	Technician N	Technician Name		Remark		
	11-02-2025 11:15:5	Neeraj Chaul	Neeraj Chauhan		Cctv survey done sales office passege 1 dome camera 2.8mm 25-30 cable requirement Trancemitar receiver signal issue		
	20-01-2025 04:58:1	.0 Shiva Meena	Shiva Meena		Camera working and cebling work completed 131 Miter		