

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5461																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9029000455																			
Technician Name :			Technician Mobile :																	
Ticket Type :	Complain	Date & Time :	16-05-2022 10:41:04																	
Vendor Details :																				
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9029000455	Name :	Ritu Gupta															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	b2 flat no 302 vdp issue																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	date : 08.05.2022 vdp power issue resolved																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-05-2022 10:42:05</td><td></td><td>Completed</td><td></td><td>-</td></tr><tr><td>16-05-2022 10:41:05</td><td></td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-05-2022 10:42:05		Completed		-	16-05-2022 10:41:05		New		-
Date Time	Technician Name	Status	Remark	Sign																
16-05-2022 10:42:05		Completed		-																
16-05-2022 10:41:05		New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-05-2022 11:09:37</td><td>Prashant Nikalje</td><td>biomax access device fps replace by biomax service center device lock alignment</td></tr><tr><td>26-04-2022 03:46:28</td><td>Ravi Rajbhar</td><td>new hdmi exdenter install and ok working done both nvr b1</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-05-2022 11:09:37	Prashant Nikalje	biomax access device fps replace by biomax service center device lock alignment	26-04-2022 03:46:28	Ravi Rajbhar	new hdmi exdenter install and ok working done both nvr b1						
Date Time	Technician Name	Remark																		
14-05-2022 11:09:37	Prashant Nikalje	biomax access device fps replace by biomax service center device lock alignment																		
26-04-2022 03:46:28	Ravi Rajbhar	new hdmi exdenter install and ok working done both nvr b1																		