


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE12346</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9820242335				
<b>Technician Name :</b>	Sonu Kumar		<b>Technician Mobile :</b>	8454016444	
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	05-08-2024 12:24:15		
<b>Vendor Details :</b>					
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile :	9820242335	Name :	Riyaz Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
Expiry Date :	01-01-1970 05:30:00		Type :		
<b>Product Name :</b>	Ppm				
<b>Complain :</b>	1 repaired camera need to install and CCTV PPM need to do				
<b>Technician Comment :</b>	1. Out gate camera install and b wing back parking cmaera install working ok 2. B wing back kichen side camera aoff issue resolved working ok and A wing front side camera off issue resolved working ok 3. B wing lift camera off issue resolved working and c wing lift camera off issue resolved working ok 4. Cctv tv ppm done 5. 2 camera collected for reparing purpose bike parking and b wing back side				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	1. Out gate camera install and b wing back parking cmaera install working ok 2. B wing back kichen side camera aoff issue resolved working ok and A wing front side camera off issue resolved working ok 3. B wing lift camera off issue resolved working and c wing lift camera off issue resolved working ok 4. Cctv tv ppm done 5. 2 camera collected for reparing purpose bike parking and b wing back side				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	20-09-2024 11:33:54	Sonu Kumar	Completed		-
	06-08-2024 02:47:36	Sonu Kumar	Work Pending	1. Out gate camera install and b wing back parking cmaera install working ok 2. B wing back kichen side camera aoff issue resolved working ok and A wing front side camera off issue resolved working ok 3. B wing lift camera off issue resolved working and c wing lift camera off issue resolved working ok 4. Cctv tv ppm done 5. 2 camera collected for reaparing purpose bike parking and b wing back side	
	05-08-2024 12:24:23	Sonu Kumar	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	23-09-2024 11:03:24				
	20-09-2024 11:40:41	Sonu Kumar	Out gate and bike parking and a wing back side camera install working ok		