

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13984																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9082608187																								
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																					
Ticket Type :	Complain	Date & Time :	31-01-2025 12:35:10																						
Vendor Details :																									
Company Name/Client Name :	MAHAVIR SQUARE	Customer's Mobile :	9082608187	Name :	Rohit Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	flat no. 1504 - VDP reinstallation (8329572272)																								
Technician Comment :	Out door camera two side crimping and vdp working normally, owner no paid installation charges.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Out door camera two side crimping and vdp working normally, owner no paid installation charges.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-02-2025 11:13:43</td><td>Rahul Mhapralkar</td><td>Completed</td><td>Out door camera two side crimping and vdp working normally, owner no paid installation charges.</td><td></td></tr><tr><td>06-02-2025 10:18:33</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr><tr><td>03-02-2025 11:58:29</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-02-2025 11:13:43	Rahul Mhapralkar	Completed	Out door camera two side crimping and vdp working normally, owner no paid installation charges.		06-02-2025 10:18:33	Rahul Mhapralkar	New		-	03-02-2025 11:58:29	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
06-02-2025 11:13:43	Rahul Mhapralkar	Completed	Out door camera two side crimping and vdp working normally, owner no paid installation charges.																						
06-02-2025 10:18:33	Rahul Mhapralkar	New		-																					
03-02-2025 11:58:29	Rahul Mhapralkar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-03-2025 11:57:16</td><td>Rahul Mhapralkar</td><td>906 flat cable continuety checking but cable issue, service lift cameras offline need to check availability for lift person</td></tr><tr><td>25-02-2025 05:27:17</td><td>Rahul Mhapralkar</td><td>Sip server connection loose, reconnection and problem resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-03-2025 11:57:16	Rahul Mhapralkar	906 flat cable continuety checking but cable issue, service lift cameras offline need to check availability for lift person	25-02-2025 05:27:17	Rahul Mhapralkar	Sip server connection loose, reconnection and problem resolved											
Date Time	Technician Name	Remark																							
01-03-2025 11:57:16	Rahul Mhapralkar	906 flat cable continuety checking but cable issue, service lift cameras offline need to check availability for lift person																							
25-02-2025 05:27:17	Rahul Mhapralkar	Sip server connection loose, reconnection and problem resolved																							