## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status D	etails: VE11329						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9765811273						
Technician Name :	Siddhesh Chavan		To :	echnician Mobile	8080922985		
Ticket Type:	Call Basis	Date & Tim	ne: 0	6-04-2024 04:19:14			
Vendor Details :	_		-				
Company Name/Client Name :	Shoppers Stop Ltd- Elpro	Customer's :	Mobile 9	765811273	Name :	Sandeep Bansode	
Address:							
pune , , , 411033	pune , , , 411033 , Maharashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00			pe:			
<b>Product Name:</b>	CCTV						
Complain:	Aurify cameras issue						
Technician Comment :	1) 1st floor check point area camera install 2) 1st floor mens footwear back store camera shifting 3) 1st floor mens footwear section camera shifting 4)ground floor watches section camera shifting done 5)cash room camera password reset done 6) 2 nvr fame rate bit rate setting done for backup increased and under observations 7)2 nvr ip setting done and ping done software install pending for client side 8) ground floor entry camera offline issue resoved						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	1) 1st floor check point area camera install 2) 1st floor mens footwear back store camera shifting 3) 1st floor mens footwear section camera shifting 4)ground floor watches section camera shifting done 5)cash room camera password reset done 6) 2 nvr fame rate bit rate setting done for backup increased and under observations 7)2 nvr ip setting done and ping done software install pending for client side 8) ground floor entry camera offline issue resoved						
Status History :	Date Time	Technician Name	Status	Re	mark	Sign	
	06-04-2024 08:00:05	Siddhesh Chavan	Completed	1) 1st floor check poinstall 2) 1st floor m store camera shiftin footwear section car 4)ground floor watch shifting done 5)cash password reset done bit rate setting done and under observati done and ping done pending for client si entry camera offline	ens footwear back g 3) 1st floor mens mera shifting hes section camera room camera e 6) 2 nvr fame rate for backup increas ons 7)2 nvr ip setti software install de 8) ground floor	sed UI	
	06-04-2024 06:42:17	Siddhesh Chavan	New			-	

Previous Complain History :

Date Time	Technician Name	Remark
31-05-2023 05:43:08	Siddhesh Chavan	
23-05-2023 06:17:47	PravinJagade	All camera working done. 2 camera install working done. Angle setting.