

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
 Support : | W : www.vallabhenterprises.com  
 E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11159</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9325275974																			
<b>Technician Name :</b>	Neeraj Chauhan	<b>Technician Mobile :</b>	8898885764																	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-03-2024 04:35:42																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Rahul International School - Boisar	<b>Customer's Mobile :</b>	9325275974	<b>Name :</b>	Sanjeet Sir															
<b>Address :</b>																				
Mumbai , boisar WEST , , 401501 , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00	<b>Type :</b>																		
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	1) A WING GATE DVR offline( GATE NO:2) 2) A WING 2nd PASSAGE camera offline 3) A WING LIBRARY CAMERA BLINKING issue 4)1 Camera from DVR Ground Floor fees counter needed to change the position Location - survey																			
<b>Technician Comment :</b>																				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	3rd floor/ 2nd floor/ 1st floor and groung floor camera angale set and 3rd floor to 2 floor/ ground floor camera angle set physical lab 2 camera issue solve																			
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>03-04-2024 01:03:37</td> <td>Neeraj Chauhan</td> <td>Completed</td> <td></td> <td>-</td> </tr> <tr> <td>19-03-2024 06:23:17</td> <td>Neeraj Chauhan</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	03-04-2024 01:03:37	Neeraj Chauhan	Completed		-	19-03-2024 06:23:17	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-04-2024 01:03:37	Neeraj Chauhan	Completed		-																
19-03-2024 06:23:17	Neeraj Chauhan	New		-																
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>11-03-2024 03:51:10</td> <td>Neeraj Chauhan</td> <td>3rd floor/ 2nd floor/ 1st floor and groung floor camera angale set and 3rd floor to 2 floor/ ground floor camera angle set physical lab 2 camera issue solve and dvr side cleaning done use 1 dc connector use ppm done</td> </tr> <tr> <td>20-02-2024 04:26:28</td> <td>PravinJagade</td> <td>Gate dvr recording working done 4 camera proper working 17 to 21 not recording 22 to 23 continue recording working done Work complete</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	11-03-2024 03:51:10	Neeraj Chauhan	3rd floor/ 2nd floor/ 1st floor and groung floor camera angale set and 3rd floor to 2 floor/ ground floor camera angle set physical lab 2 camera issue solve and dvr side cleaning done use 1 dc connector use ppm done	20-02-2024 04:26:28	PravinJagade	Gate dvr recording working done 4 camera proper working 17 to 21 not recording 22 to 23 continue recording working done Work complete						
Date Time	Technician Name	Remark																		
11-03-2024 03:51:10	Neeraj Chauhan	3rd floor/ 2nd floor/ 1st floor and groung floor camera angale set and 3rd floor to 2 floor/ ground floor camera angle set physical lab 2 camera issue solve and dvr side cleaning done use 1 dc connector use ppm done																		
20-02-2024 04:26:28	PravinJagade	Gate dvr recording working done 4 camera proper working 17 to 21 not recording 22 to 23 continue recording working done Work complete																		