




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

| Service Status Details : VE12063 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--|--|---|---|-------------|-----------|-----------------|--------|---------------------|------------|--|---------------------|------------|---|---|---------------------|------------|-----|--|---|---------------------|------------|-----|--|---|---------------------|------------|-----|--|---|
| Priority : | Low | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Created By : | Admin - Apurva Vajaria | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Complaint Mob. No. : | 9325275974 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Technician Name : | Sonu Kumar | | Technician Mobile : | 8454016444 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Ticket Type : | Complain | Date & Time : | 04-07-2024 12:15:27 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Vendor Details : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Company Name/Client Name : | Rahul International School - Boisar | Customer's Mobile : | 9325275974 | Name : | Sanjeet Sir | | | | | | | | | | | | | | | | | | | | | | | | | |
| Address : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Mumbai , boisar WEST , , 401501 , Maharashtra | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| AMC Details : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Type : | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Product Name : | CCTV | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Complain : | A wing 2nd floor 5 camera off issue | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Technician Comment : | 2nd floor 5 camera off issue resolved working ok and al dvr ppm done with one dome camera taking and power supply | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Remark : | 2nd floor 5 camera off issue resolved working ok and al dvr ppm done with one dome camera taking and power supply | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Status History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-07-2024 02:42:19</td><td>Sonu Kumar</td><td>Completed</td><td>2nd floor 5 camera off issue resolved working ok and al dvr ppm done with one dome camera taking and power supply</td><td></td></tr><tr><td>11-07-2024 11:20:22</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>10-07-2024 12:17:08</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>06-07-2024 06:13:08</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table> | | | | | Date Time | Technician Name | Status | Remark | Sign | 11-07-2024 02:42:19 | Sonu Kumar | Completed | 2nd floor 5 camera off issue resolved working ok and al dvr ppm done with one dome camera taking and power supply |  | 11-07-2024 11:20:22 | Sonu Kumar | New | | - | 10-07-2024 12:17:08 | Sonu Kumar | New | | - | 06-07-2024 06:13:08 | Sonu Kumar | New | | - |
| Date Time | Technician Name | Status | Remark | Sign | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11-07-2024 02:42:19 | Sonu Kumar | Completed | 2nd floor 5 camera off issue resolved working ok and al dvr ppm done with one dome camera taking and power supply |  | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11-07-2024 11:20:22 | Sonu Kumar | New | | - | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10-07-2024 12:17:08 | Sonu Kumar | New | | - | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 06-07-2024 06:13:08 | Sonu Kumar | New | | - | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Previous Complain History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-08-2024 05:33:55</td><td>Sonu Kumar</td><td>2nd floor dvr adupter change working ok and 3rd floor passage camera install and 2nd floor stair case camera install Need one IP Camera.</td></tr><tr><td>10-07-2024 12:18:30</td><td>Sonu Kumar</td><td>2nd floor ppm and 3rd floor ppm done</td></tr></tbody></table> | | | | | Date Time | Technician Name | Remark | 10-08-2024 05:33:55 | Sonu Kumar | 2nd floor dvr adupter change working ok and 3rd floor passage camera install and 2nd floor stair case camera install Need one IP Camera. | 10-07-2024 12:18:30 | Sonu Kumar | 2nd floor ppm and 3rd floor ppm done | | | | | | | | | | | | | | | | |
| Date Time | Technician Name | Remark | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10-08-2024 05:33:55 | Sonu Kumar | 2nd floor dvr adupter change working ok and 3rd floor passage camera install and 2nd floor stair case camera install Need one IP Camera. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10-07-2024 12:18:30 | Sonu Kumar | 2nd floor ppm and 3rd floor ppm done | | | | | | | | | | | | | | | | | | | | | | | | | | | | |