


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2716					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9821745351				
Technician Name :	Rishi Desai		Technician Mobile :	8369234074	
Ticket Type :	Complain	Date & Time :	20-02-2021 10:15:11		
Vendor Details :					
Company Name/Client Name :	Mehta Kunj - Rite Developers	Customer's Mobile :	9821745351	Name :	Sanjeev Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Ppm				
Complain :	Intercom ppm				
Technician Comment :	Intercom system checked, Flat to Flat checkedbthe system checked. Total 22 Flats 101 - instrument issue 102 - instrument issue 103 - ok 104 - Line issue 201 - Line issue 202 - ok 203 - ok 301 - ok 302 - ok 303 - ok 401 - instrument issue 402 - ok 403 - instrument issue 501 - ok 502 - ok 503 - ok 601 - ok 602 - ok 603 - ok 701 - instrument issue 702 - ok 703 - instrument issue 99 number of reception is started and also merged with security cabin . work completed.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Intercom system checked, Flat to Flat checkedbthe system checked. Total 22 Flats 101 - instrument issue 102 - instrument issue 103 - ok 104 - Line issue 201 - Line issue 202 - ok 203 - ok 301 - ok 302 - ok 303 - ok 401 - instrument issue 402 - ok 403 - instrument issue 501 - ok 502 - ok 503 - ok 601 - ok 602 - ok 603 - ok 701 - instrument issue 702 - ok 703 - instrument issue 99 number of reception is started and also merged with security cabin . work completed.				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	20-02-2021 02:13:08	RishiDesai	Completed	Intercom system checked, Flat to Flat checkedbthe system checked. Total 22 Flats 101 - instrument issue 102 - instrument issue 103 - ok 104 - Line issue 201 - Line issue 202 - ok 203 - ok 301 - ok 302 - ok 303 - ok 401 - instrument issue 402 - ok 403 - instrument issue 501 - ok 502 - ok 503 - ok 601 - ok 602 - ok 603 - ok 701 - instrument issue 702 - ok 703 - instrument issue 99 number of reception is started and also merged with security cabin . work completed.	
	20-02-2021 10:15:37	RishiDesai	New		-
	20-02-2021 10:15:11	RishiDesai	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	12-05-2023 03:27:21	Kalpesh SubhashGurav	PPM Done		
	21-03-2023 03:45:00	Sonu Kumar	99 intercom issue resolved working ok and 402intercom issue resolved working ok and intercom 100 line ok instrument speaker issue		