




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3500</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	7798321220																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	27-07-2021 12:58:05																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Armstrong (India) Constructions	Customer's Mobile :	7798321220	Name :	Sanket Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Access																								
<b>Complain :</b>	exit switch not working of main enterance																								
<b>Technician Comment :</b>	main cabin exit switch issue resolved and ok working done only cable issue exit switch and reception line ok instrument keypaid issue																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	main cabin exit switch issue resolved and ok working done only cable issue exit switch and reception line ok instrument keypaid issue																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-07-2021 02:11:07</td><td>Ravi Rajbhar</td><td>Completed</td><td>main cabin exit switch issue resolved and ok working done only cable issue exit switch and reception line ok instrument keypaid issue</td><td></td></tr><tr><td>27-07-2021 12:58:18</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>27-07-2021 12:58:06</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-07-2021 02:11:07	Ravi Rajbhar	Completed	main cabin exit switch issue resolved and ok working done only cable issue exit switch and reception line ok instrument keypaid issue		27-07-2021 12:58:18	Ravi Rajbhar	New		-	27-07-2021 12:58:06	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
27-07-2021 02:11:07	Ravi Rajbhar	Completed	main cabin exit switch issue resolved and ok working done only cable issue exit switch and reception line ok instrument keypaid issue																						
27-07-2021 12:58:18	Ravi Rajbhar	New		-																					
27-07-2021 12:58:06	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-06-2023 10:19:51</td><td>Sonu Kumar</td><td>CCTV ppm done and intercom ppm done</td></tr><tr><td>17-05-2023 10:44:26</td><td>Prashant Nikalje</td><td>prashant old visited site 18.05.2023 office out side camera issued resolved replace camera</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-06-2023 10:19:51	Sonu Kumar	CCTV ppm done and intercom ppm done	17-05-2023 10:44:26	Prashant Nikalje	prashant old visited site 18.05.2023 office out side camera issued resolved replace camera											
Date Time	Technician Name	Remark																							
12-06-2023 10:19:51	Sonu Kumar	CCTV ppm done and intercom ppm done																							
17-05-2023 10:44:26	Prashant Nikalje	prashant old visited site 18.05.2023 office out side camera issued resolved replace camera																							