

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7178																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7798321220																			
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																
Ticket Type :	AMC visiting	Date & Time :	24-12-2022 11:26:00																	
Vendor Details :																				
Company Name/Client Name :	Armstrong (India) Constructions	Customer's Mobile :	7798321220	Name :	Sanket Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Ppm																			
Complain :	CCTV / Intercom need to do ppm																			
Technician Comment :	dressing done dvr side. 2 camera install. production room intercome cable find 2 cable working line ok. gest room and 2 driver room cable breck.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	dressing done dvr side. 2 camera install. production room intercome cable find 2 cable working line ok. gest room and 2 driver room cable breck.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-12-2022 06:06:36</td><td>PravinJagade</td><td>Completed</td><td>dressing done dvr side. 2 camera install. production room intercome cable find 2 cable working line ok. gest room and 2 driver room cable breck.</td><td></td></tr><tr><td>24-12-2022 11:27:23</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-12-2022 06:06:36	PravinJagade	Completed	dressing done dvr side. 2 camera install. production room intercome cable find 2 cable working line ok. gest room and 2 driver room cable breck.		24-12-2022 11:27:23	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-12-2022 06:06:36	PravinJagade	Completed	dressing done dvr side. 2 camera install. production room intercome cable find 2 cable working line ok. gest room and 2 driver room cable breck.																	
24-12-2022 11:27:23	PravinJagade	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-12-2022 01:03:07</td><td>PravinJagade</td><td>camera replace. 1. boss cabine dome. 2. reseption area dome. 3. dvr room dome. 4. store room bullet 5. sand material area bullet 2 rojet box install. 4 RJ 11 connector use. 3 dc and 3 BNC use. 3 meter cable use. 3 intercome cable not working cable not found. production room 2 intercome connect working k. 3 intercom cable distance 180</td></tr><tr><td>12-10-2022 10:56:16</td><td>Shiva Meena</td><td>ppm done</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-12-2022 01:03:07	PravinJagade	camera replace. 1. boss cabine dome. 2. reseption area dome. 3. dvr room dome. 4. store room bullet 5. sand material area bullet 2 rojet box install. 4 RJ 11 connector use. 3 dc and 3 BNC use. 3 meter cable use. 3 intercome cable not working cable not found. production room 2 intercome connect working k. 3 intercom cable distance 180	12-10-2022 10:56:16	Shiva Meena	ppm done						
Date Time	Technician Name	Remark																		
26-12-2022 01:03:07	PravinJagade	camera replace. 1. boss cabine dome. 2. reseption area dome. 3. dvr room dome. 4. store room bullet 5. sand material area bullet 2 rojet box install. 4 RJ 11 connector use. 3 dc and 3 BNC use. 3 meter cable use. 3 intercome cable not working cable not found. production room 2 intercome connect working k. 3 intercom cable distance 180																		
12-10-2022 10:56:16	Shiva Meena	ppm done																		