

karvy technologies pvt.ltd

Regd. Office :
Support : | W :
E : info@karvytech.in

Service Status Details : TRI9															
Priority :	High														
Created By :	Admin - Karim														
Complaint Mob. No. :	8697722147														
Technician Name :			Technician Mobile :												
Ticket Type :	Complain	Date & Time :	29-07-2021 11:59:40												
Vendor Details :															
Company Name/Client Name :	WSG-Sarat Bose Road	Customer's Mobile :	8697722147	Name :	Soumen										
Address :															
Kolkata , , , West Bengal															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	Interlocking Control System														
Complain :	THE MAIN VAULT GATE EXIT SWITCH IS NOT WORKING PROPERLY														
Technician Comment :															
Complain Operator :	Desktop - Karim														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-07-2021 11:59:40</td><td></td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-07-2021 11:59:40		New		-
Date Time	Technician Name	Status	Remark	Sign											
29-07-2021 11:59:40		New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2021 11:57:58</td><td></td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2021 11:57:58						
Date Time	Technician Name	Remark													
29-07-2021 11:57:58															