







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10919</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820612503																													
<b>Technician Name :</b>	Shiva Meena		<b>Technician Mobile :</b>	7489567735																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-02-2024 11:27:48																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Saikripa Auto And Oil Center	<b>Customer's Mobile :</b>	9820612503	<b>Name :</b>	Subhash Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	1)1 camera reinstallation with cabling 2)2 old cameras cabling 3)USB Extender need to install for old DVR CNG To petrol pump viewing																													
<b>Technician Comment :</b>	1 camera ricnecasan done and tv work and maus work complete 2rj45 cenecatr us																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	1 camera ricnecasan done and tv work and maus work complete 2rj45 cenecatr us																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-03-2024 04:17:09</td><td>Shiva Meena</td><td>Completed</td><td>1 camera ricnecasan done and tv work and maus work complete 2rj45 cenecatr us</td><td></td></tr><tr><td>11-03-2024 02:06:43</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>07-03-2024 05:54:31</td><td>Shiva Meena</td><td>Work Pending</td><td>Dvr 32 channel Working camera 17 Petrol pump 32 channel Dvr 15 camera working 1 usb extendar issue 1 vga extender issue( CNG) Nvr Rack fan not working 8 channel dvr Working camera 06</td><td></td></tr><tr><td>05-03-2024 11:14:07</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-03-2024 04:17:09	Shiva Meena	Completed	1 camera ricnecasan done and tv work and maus work complete 2rj45 cenecatr us		11-03-2024 02:06:43	Shiva Meena	New		-	07-03-2024 05:54:31	Shiva Meena	Work Pending	Dvr 32 channel Working camera 17 Petrol pump 32 channel Dvr 15 camera working 1 usb extendar issue 1 vga extender issue( CNG) Nvr Rack fan not working 8 channel dvr Working camera 06		05-03-2024 11:14:07	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																										
11-03-2024 04:17:09	Shiva Meena	Completed	1 camera ricnecasan done and tv work and maus work complete 2rj45 cenecatr us																											
11-03-2024 02:06:43	Shiva Meena	New		-																										
07-03-2024 05:54:31	Shiva Meena	Work Pending	Dvr 32 channel Working camera 17 Petrol pump 32 channel Dvr 15 camera working 1 usb extendar issue 1 vga extender issue( CNG) Nvr Rack fan not working 8 channel dvr Working camera 06																											
05-03-2024 11:14:07	Shiva Meena	New		-																										

Previous Complain History :			
	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>
	27-02-2024 01:02:29	Neeraj Chauhan	Petrol pump 1 camera New cabling and camera installation and again install and 1 camera now vide issue solve angle setting 2 camera 1camera Reconnection 1camera angle setting and CNG pump 1 camera housing Reinstall.
	29-01-2024 01:05:48	PravinJagade	Cng dvr Channal no 1 camera no video issue resolve working done. Channal no 7/8 cable falty. Petrol pump side 1 camera shift and 1 camera angle setting done Cng dvr not mous operat petrol pump office need to check pending Cng side pipe hanging pending Petrol pump 2 camera shifting pending. Cng chqnnal no 1 camera black and white next visit to change.