




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11988																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820612503																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	Complain	Date & Time :	25-06-2024 12:50:54																	
Vendor Details :																				
Company Name/Client Name :	Saikripa Auto And Oil Center	Customer's Mobile :	9820612503	Name :	Subhash Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	CNG Monitor from 1st floor need to shift in ground floor and in CNG office 1camera need to extend - survey need to do																			
Technician Comment :	Tv and 1 camera survey done and CNG pump camera no 12 no video issue																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Tv and 1 camera survey done and CNG pump camera no 12 no video issue																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-06-2024 10:54:05</td><td>Neeraj Chauhan</td><td>Completed</td><td>Tv and 1 camera survey done and CNG pump camera no 12 no video issue</td><td></td></tr><tr><td>25-06-2024 06:39:37</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-06-2024 10:54:05	Neeraj Chauhan	Completed	Tv and 1 camera survey done and CNG pump camera no 12 no video issue		25-06-2024 06:39:37	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-06-2024 10:54:05	Neeraj Chauhan	Completed	Tv and 1 camera survey done and CNG pump camera no 12 no video issue																	
25-06-2024 06:39:37	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-09-2024 02:52:12</td><td></td><td></td></tr><tr><td>23-09-2024 10:07:01</td><td>Neeraj Chauhan</td><td>2 camera no video issue solve and 1 camera replace and office issue solve and use 1 nos video balune and doc conector</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-09-2024 02:52:12			23-09-2024 10:07:01	Neeraj Chauhan	2 camera no video issue solve and 1 camera replace and office issue solve and use 1 nos video balune and doc conector						
Date Time	Technician Name	Remark																		
25-09-2024 02:52:12																				
23-09-2024 10:07:01	Neeraj Chauhan	2 camera no video issue solve and 1 camera replace and office issue solve and use 1 nos video balune and doc conector																		