




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

| Service Status Details : VE13146 | | | | | | | | | | | | | | | | | | | | |
|---|---|--|--|---|-----------|-----------|-----------------|--------|---------------------|--------------|--|---------------------|--------------|--|---|---------------------|--------------|-----|--|---|
| Priority : | Low | | | | | | | | | | | | | | | | | | | |
| Created By : | Admin - Apurva Vajaria | | | | | | | | | | | | | | | | | | | |
| Complaint Mob. No. : | 9820577881 | | | | | | | | | | | | | | | | | | | |
| Technician Name : | Ravi Rajbhar | | Technician Mobile : | 8080922965 | | | | | | | | | | | | | | | | |
| Ticket Type : | Complain | Date & Time : | 30-10-2024 10:49:17 | | | | | | | | | | | | | | | | | |
| Vendor Details : | | | | | | | | | | | | | | | | | | | | |
| Company Name/Client Name : | Manglik Co Op Hsg Society Ltd | Customer's Mobile : | 9820577881 | Name : | Suhas Sir | | | | | | | | | | | | | | | |
| Address : | | | | | | | | | | | | | | | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | | | | | | | | | | | | | | | |
| AMC Details : | | | | | | | | | | | | | | | | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Type : | | | | | | | | | | | | | | | | | |
| Product Name : | Intercom | | | | | | | | | | | | | | | | | | | |
| Complain : | 3-4 flats intercom issue | | | | | | | | | | | | | | | | | | | |
| Technician Comment : | Flat no. 602 intercom issue resolved And 701 line ok instrument issue speekar 501 line ok instrument issue Both lift intercom ok working infrom to suhas sir | | | | | | | | | | | | | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | | | | | | | | | | | | | |
| Remark : | Flat no. 602 intercom issue resolved And 701 line ok instrument issue speekar 501 line ok instrument issue Both lift intercom ok working infrom to suhas sir | | | | | | | | | | | | | | | | | | | |
| Status History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-10-2024 11:50:16</td><td>Ravi Rajbhar</td><td>Completed</td><td>Flat no. 602 intercom issue resolved And 701 line ok instrument issue speekar 501 line ok instrument issue Both lift intercom ok working infrom to suhas sir</td><td></td></tr><tr><td>30-10-2024 10:55:48</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table> | | | | | Date Time | Technician Name | Status | Remark | Sign | 30-10-2024 11:50:16 | Ravi Rajbhar | Completed | Flat no. 602 intercom issue resolved And 701 line ok instrument issue speekar 501 line ok instrument issue Both lift intercom ok working infrom to suhas sir |  | 30-10-2024 10:55:48 | Ravi Rajbhar | New | | - |
| Date Time | Technician Name | Status | Remark | Sign | | | | | | | | | | | | | | | | |
| 30-10-2024 11:50:16 | Ravi Rajbhar | Completed | Flat no. 602 intercom issue resolved And 701 line ok instrument issue speekar 501 line ok instrument issue Both lift intercom ok working infrom to suhas sir |  | | | | | | | | | | | | | | | | |
| 30-10-2024 10:55:48 | Ravi Rajbhar | New | | - | | | | | | | | | | | | | | | | |
| Previous Complain History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-12-2024 10:16:38</td><td>PravinJagade</td><td>2 camera shifting done. Tv location change tv shifting done. 65 meter cabling done. 2 camera and 1 mous and tv view. All camera proper working. 2 per video ballon use/ 2 RJ 45 connector use.</td></tr><tr><td>13-11-2024 01:23:14</td><td>PravinJagade</td><td>1 camera off issue resolved working done. And 2 camera shifting servay done.</td></tr></tbody></table> | | | | | Date Time | Technician Name | Remark | 02-12-2024 10:16:38 | PravinJagade | 2 camera shifting done. Tv location change tv shifting done. 65 meter cabling done. 2 camera and 1 mous and tv view. All camera proper working. 2 per video ballon use/ 2 RJ 45 connector use. | 13-11-2024 01:23:14 | PravinJagade | 1 camera off issue resolved working done. And 2 camera shifting servay done. | | | | | | |
| Date Time | Technician Name | Remark | | | | | | | | | | | | | | | | | | |
| 02-12-2024 10:16:38 | PravinJagade | 2 camera shifting done. Tv location change tv shifting done. 65 meter cabling done. 2 camera and 1 mous and tv view. All camera proper working. 2 per video ballon use/ 2 RJ 45 connector use. | | | | | | | | | | | | | | | | | | |
| 13-11-2024 01:23:14 | PravinJagade | 1 camera off issue resolved working done. And 2 camera shifting servay done. | | | | | | | | | | | | | | | | | | |