

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13951																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820577881																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	Complain	Date & Time :	28-01-2025 10:40:54																	
Vendor Details :																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Need to shift rack for dvr need to do survey																			
Technician Comment :	Dvr rack shifting survey done shifting place electric supply requirement 10 mtr back shifting																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Dvr rack shifting survey done shifting place electric supply requirement 10 mtr back shifting																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-01-2025 02:43:09</td><td>Neeraj Chauhan</td><td>Completed</td><td>Dvr rack shifting survey done shifting place electric supply requirement 10 mtr back shifting</td><td></td></tr><tr><td>28-01-2025 10:47:55</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-01-2025 02:43:09	Neeraj Chauhan	Completed	Dvr rack shifting survey done shifting place electric supply requirement 10 mtr back shifting		28-01-2025 10:47:55	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-01-2025 02:43:09	Neeraj Chauhan	Completed	Dvr rack shifting survey done shifting place electric supply requirement 10 mtr back shifting																	
28-01-2025 10:47:55	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-01-2025 03:10:18</td><td>ChandanYadav</td><td>one camera joined the cakble and camera working ok.</td></tr><tr><td>07-01-2025 05:19:54</td><td>ChandanYadav</td><td>one camera cakble joined camera working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-01-2025 03:10:18	ChandanYadav	one camera joined the cakble and camera working ok.	07-01-2025 05:19:54	ChandanYadav	one camera cakble joined camera working ok.						
Date Time	Technician Name	Remark																		
13-01-2025 03:10:18	ChandanYadav	one camera joined the cakble and camera working ok.																		
07-01-2025 05:19:54	ChandanYadav	one camera cakble joined camera working ok.																		