




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE14169</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9820577881																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	26-02-2025 02:32:19																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	flat no. 403 phone need to change and charges need to collect and 1 camera cable break need to joint the same																			
<b>Technician Comment :</b>	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-02-2025 03:56:19</td><td>Ravi Rajbhar</td><td>Completed</td><td>Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done</td><td></td></tr><tr><td>26-02-2025 02:32:28</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-02-2025 03:56:19	Ravi Rajbhar	Completed	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done		26-02-2025 02:32:28	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-02-2025 03:56:19	Ravi Rajbhar	Completed	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done																	
26-02-2025 02:32:28	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-03-2025 02:50:48</td><td>ManojPolekar</td><td>All camera dismental work done</td></tr><tr><td>28-02-2025 11:02:55</td><td>Neeraj Chauhan</td><td>Sitting done All system shift to other place system working okk</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-03-2025 02:50:48	ManojPolekar	All camera dismental work done	28-02-2025 11:02:55	Neeraj Chauhan	Sitting done All system shift to other place system working okk						
Date Time	Technician Name	Remark																		
03-03-2025 02:50:48	ManojPolekar	All camera dismental work done																		
28-02-2025 11:02:55	Neeraj Chauhan	Sitting done All system shift to other place system working okk																		