

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14181																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820577881																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	Complain	Date & Time :	28-02-2025 11:02:55																	
Vendor Details :																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	TV and DVR need to dismantle																			
Technician Comment :	Sitting done All system shift to other place system working okk																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Sitting done All system shift to other place system working okk																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-02-2025 12:43:08</td><td>Neeraj Chauhan</td><td>Completed</td><td>Sitting done All system shift to other place system working okk</td><td></td></tr><tr><td>28-02-2025 11:03:52</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-02-2025 12:43:08	Neeraj Chauhan	Completed	Sitting done All system shift to other place system working okk		28-02-2025 11:03:52	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-02-2025 12:43:08	Neeraj Chauhan	Completed	Sitting done All system shift to other place system working okk																	
28-02-2025 11:03:52	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-03-2025 02:50:48</td><td>ManojPolekar</td><td>All camera dismental work done</td></tr><tr><td>26-02-2025 02:32:19</td><td>Ravi Rajbhar</td><td>Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-03-2025 02:50:48	ManojPolekar	All camera dismental work done	26-02-2025 02:32:19	Ravi Rajbhar	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done						
Date Time	Technician Name	Remark																		
03-03-2025 02:50:48	ManojPolekar	All camera dismental work done																		
26-02-2025 02:32:19	Ravi Rajbhar	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done																		