

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14206																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820577881																			
Technician Name :	Manoj Polekar		Technician Mobile :	7385366458																
Ticket Type :	Complain	Date & Time :	03-03-2025 02:50:48																	
Vendor Details :																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	all cameras need to dismantle																			
Technician Comment :	All camera dismental work done																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	All camera dismental work done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-03-2025 04:18:35</td><td>ManojPolekar</td><td>Completed</td><td>All camera dismental work done</td><td></td></tr><tr><td>03-03-2025 02:51:05</td><td>ManojPolekar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-03-2025 04:18:35	ManojPolekar	Completed	All camera dismental work done		03-03-2025 02:51:05	ManojPolekar	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-03-2025 04:18:35	ManojPolekar	Completed	All camera dismental work done																	
03-03-2025 02:51:05	ManojPolekar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-02-2025 11:02:55</td><td>Neeraj Chauhan</td><td>Sitting done All system shift to other place system working okk</td></tr><tr><td>26-02-2025 02:32:19</td><td>Ravi Rajbhar</td><td>Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-02-2025 11:02:55	Neeraj Chauhan	Sitting done All system shift to other place system working okk	26-02-2025 02:32:19	Ravi Rajbhar	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done						
Date Time	Technician Name	Remark																		
28-02-2025 11:02:55	Neeraj Chauhan	Sitting done All system shift to other place system working okk																		
26-02-2025 02:32:19	Ravi Rajbhar	Flat no. 403 new insument install with faulty hondover to client And one cmaera cable joint back side parking area All ok working done																		