

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2453																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820577881																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	19-12-2020 11:23:57																	
Vendor Details :																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	install phone in 1001 and collect cash																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-12-2020 11:24:13</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>19-12-2020 11:23:58</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-12-2020 11:24:13	Siddhesh Chavan	New		-	19-12-2020 11:23:58	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
19-12-2020 11:24:13	Siddhesh Chavan	New		-																
19-12-2020 11:23:58	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 01:25:15</td><td>Ravi Rajbhar</td><td>202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23</td></tr><tr><td>20-07-2023 01:23:14</td><td>Kalpesh SubhashGurav</td><td>Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23	20-07-2023 01:23:14	Kalpesh SubhashGurav	Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset						
Date Time	Technician Name	Remark																		
29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																		
20-07-2023 01:23:14	Kalpesh SubhashGurav	Security Ext.99 Problem Solved Extra Ringer Installed Main Gate Camera No.11 Angleset																		