




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11211																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9113346616																			
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																
Ticket Type :	Call Basis	Date & Time :	23-03-2024 01:12:42																	
Vendor Details :																				
Company Name/Client Name :	Vasant Villa CHS	Customer's Mobile :	9113346616	Name :	Suraj Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	backside camera cabling need to do																			
Technician Comment :	78 miter cebaling work and camera work complete dvr said canecsan done work complete																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	78 miter cebaling work and camera work complete dvr said canecsan done work complete																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-03-2024 04:36:32</td><td>Shiva Meena</td><td>Completed</td><td>78 miter cebaling work and camera work complete dvr said canecsan done work complete</td><td></td></tr><tr><td>26-03-2024 10:25:03</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-03-2024 04:36:32	Shiva Meena	Completed	78 miter cebaling work and camera work complete dvr said canecsan done work complete		26-03-2024 10:25:03	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-03-2024 04:36:32	Shiva Meena	Completed	78 miter cebaling work and camera work complete dvr said canecsan done work complete																	
26-03-2024 10:25:03	Shiva Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-03-2024 11:13:07</td><td>Ravi Rajbhar</td><td>8A intercom line ok instrument issue and society office also ok working done and one cmaera back side cable faulty need to change also infrom to atik</td></tr><tr><td>12-03-2024 10:34:28</td><td>Atique Salmani</td><td>Main gate camera cable was break find out from above forceling cut cable rejoint and working ok set angel and back side gate also cable break didn't found from where cable cut so painding if new cabling need to do 70/80 metr cable 4+1 .</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-03-2024 11:13:07	Ravi Rajbhar	8A intercom line ok instrument issue and society office also ok working done and one cmaera back side cable faulty need to change also infrom to atik	12-03-2024 10:34:28	Atique Salmani	Main gate camera cable was break find out from above forceling cut cable rejoint and working ok set angel and back side gate also cable break didn't found from where cable cut so painding if new cabling need to do 70/80 metr cable 4+1 .						
Date Time	Technician Name	Remark																		
22-03-2024 11:13:07	Ravi Rajbhar	8A intercom line ok instrument issue and society office also ok working done and one cmaera back side cable faulty need to change also infrom to atik																		
12-03-2024 10:34:28	Atique Salmani	Main gate camera cable was break find out from above forceling cut cable rejoint and working ok set angel and back side gate also cable break didn't found from where cable cut so painding if new cabling need to do 70/80 metr cable 4+1 .																		