

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3111</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9769402476				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	22-05-2021 09:50:18		
<b>Vendor Details :</b>					
Company Name/Client Name :	Vasant Villa CHS	Customer's Mobile :	9769402476	Name :	Suraj Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive	
<b>Product Name :</b>	Ppm				
<b>Complain :</b>	cctv / intercom				
<b>Technician Comment :</b>	ppm of CCTV and intercom done all cameras lence cleandvr end also and also complain of intercom flate nmbr 17 and 9 nmbr flate nmbr 17 was phone removed so installed phone after check the line ok. and flate nmbr 9 there is cable missing from flate to duct so drop 5/6 mtr cable and punch in crone line ok but need one instrument with rozer box and client redy to pay. for instrument				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	ppm of CCTV and intercom done all cameras lence cleandvr end also and also complain of intercom flate nmbr 17 and 9 nmbr flate nmbr 17 was phone removed so installed phone after check the line ok. and flate nmbr 9 there is cable missing from flate to duct so drop 5/6 mtr cable and punch in crone line ok but need one instrument with rozer box and client redy to pay. for instrument				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	22-05-2021 01:47:09	Atique Salmani	Completed	ppm of CCTV and intercom done all cameras lence cleandvr end also and also complain of intercom flate nmbr 17 and 9 nmbr flate nmbr 17 was phone removed so installed phone after check the line ok. and flate nmbr 9 there is cable missing from flate to duct so drop 5/6 mtr cable and punch in crone line ok but need one instrument with rozer box and client redy to pay. for instrument	H 2157
	22-05-2021 09:50:50	Atique Salmani	New		-
	22-05-2021 09:50:18	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	08-08-2023 04:32:00	InzmamUl Haq			
	25-07-2023 10:30:39	Kalpesh SubhashGurav	Camera No. 13 Problem Solved Working Done.		