

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15478																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9922942248																								
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																					
Ticket Type :	Complain	Date & Time :	04-08-2025 10:59:45																						
Vendor Details :																									
Company Name/Client Name :	Brookhil Chs	Customer's Mobile :	9922942248	Name :	Swati Mam																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	1)Main Gate intercom issue 2)Flat no. 1701 intercom issue																								
Technician Comment :	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-08-2025 12:44:02</td><td>Rahul Mhapralkar</td><td>Completed</td><td>2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777</td><td></td></tr><tr><td>04-08-2025 12:44:02</td><td>Rahul Mhapralkar</td><td>Completed</td><td>2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777</td><td></td></tr><tr><td>04-08-2025 10:59:52</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-08-2025 12:44:02	Rahul Mhapralkar	Completed	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777		04-08-2025 12:44:02	Rahul Mhapralkar	Completed	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777		04-08-2025 10:59:52	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-08-2025 12:44:02	Rahul Mhapralkar	Completed	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777																						
04-08-2025 12:44:02	Rahul Mhapralkar	Completed	2401,2601,1401 flat owner finger print add nd 2601,2503,1705 flat Intercom complaint resolved, 1701 flat no intercom number dail 777																						
04-08-2025 10:59:52	Rahul Mhapralkar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-08-2025 10:46:33</td><td>Rahul Mhapralkar</td><td></td></tr><tr><td>23-07-2025 10:13:09</td><td>Rahul Mhapralkar</td><td>Finger print delete 1305/2601/2605/403/1401</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-08-2025 10:46:33	Rahul Mhapralkar		23-07-2025 10:13:09	Rahul Mhapralkar	Finger print delete 1305/2601/2605/403/1401											
Date Time	Technician Name	Remark																							
01-08-2025 10:46:33	Rahul Mhapralkar																								
23-07-2025 10:13:09	Rahul Mhapralkar	Finger print delete 1305/2601/2605/403/1401																							