




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE960</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	7045879751																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	23-01-2020 11:27:01																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Parija Apartment	Customer's Mobile :	7045879751	Name :	Vaswani Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	19-01-2020 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	one camera not able to view																								
<b>Technician Comment :</b>	one camera back side not working check and issue resolved and nowvall cctv system working ok.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	one camera back side not working check and issue resolved and nowvall cctv system working ok.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-01-2020 12:01:27</td><td>Atique Salmani</td><td>Completed</td><td>one camera back side not working check and issue resolved and nowvall cctv system working ok.</td><td></td></tr><tr><td>23-01-2020 11:27:09</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>23-01-2020 11:27:02</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-01-2020 12:01:27	Atique Salmani	Completed	one camera back side not working check and issue resolved and nowvall cctv system working ok.		23-01-2020 11:27:09	Atique Salmani	New		-	23-01-2020 11:27:02	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-01-2020 12:01:27	Atique Salmani	Completed	one camera back side not working check and issue resolved and nowvall cctv system working ok.																						
23-01-2020 11:27:09	Atique Salmani	New		-																					
23-01-2020 11:27:02	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-01-2020 05:43:52</td><td>Siddhesh Chavan</td><td>new dvr install and frame rate and bit rate set time and date set and working ok</td></tr><tr><td>19-08-2019 12:11:39</td><td>Atique Salmani</td><td>there is camera end issue joint of camera rushted as a fungus so cut the cable and reconnection and also angel set and also recording symbol on display plyback didn't check becoz mouse not available at site. ita camera no. 3and maingate ne security table</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-01-2020 05:43:52	Siddhesh Chavan	new dvr install and frame rate and bit rate set time and date set and working ok	19-08-2019 12:11:39	Atique Salmani	there is camera end issue joint of camera rushted as a fungus so cut the cable and reconnection and also angel set and also recording symbol on display plyback didn't check becoz mouse not available at site. ita camera no. 3and maingate ne security table											
Date Time	Technician Name	Remark																							
03-01-2020 05:43:52	Siddhesh Chavan	new dvr install and frame rate and bit rate set time and date set and working ok																							
19-08-2019 12:11:39	Atique Salmani	there is camera end issue joint of camera rushted as a fungus so cut the cable and reconnection and also angel set and also recording symbol on display plyback didn't check becoz mouse not available at site. ita camera no. 3and maingate ne security table																							