





Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15688					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7718815774				
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965	
Ticket Type :	Complain	Date & Time :	01-09-2025 02:02:06		
Vendor Details :					
Company Name/Client Name :	Apparel Group (India) Private Limited	Customer's Mobile :	7718815774	Name :	Vijay Pal
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Access				
Complain :	access lock need to check				
Technician Comment :	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	05-09-2025 04:17:54	Ravi Rajbhar	Completed	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????	
	05-09-2025 04:17:53	Ravi Rajbhar	Completed	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????	
	01-09-2025 03:51:17	Ravi Rajbhar	Completed	Apparel group no touch ok working but client told need to change bcz no touch blue light not show proper on front	
	01-09-2025 03:51:17	Ravi Rajbhar	Completed	Apparel group no touch ok working but client told need to change bcz no touch blue light not show proper on front	
	01-09-2025 02:02:15	Ravi Rajbhar	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	13-08-2024 11:19:33	Atique Salmani	Reception table exit swich connection done working ok.		
	31-05-2024 06:20:25	MayurYadav	Mumbai 2 device online data download Delhi 2 Device added online in process		