




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1510																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9819990297																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	01-07-2020 07:08:37																						
Vendor Details :																									
Company Name/Client Name :	Bhoomi Ganga Enclave A Wing	Customer's Mobile :	9819990297	Name :	Vipul Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	VDP																								
Complain :	102 out camera bought to ofc which is need to be installed after repairing																								
Technician Comment :	out door camera installed and working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	out door camera installed and working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-07-2020 07:42:22</td><td>Atique Salmani</td><td>Completed</td><td>out door camera installed and working ok.</td><td></td></tr><tr><td>01-07-2020 07:09:03</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>01-07-2020 07:08:38</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-07-2020 07:42:22	Atique Salmani	Completed	out door camera installed and working ok.		01-07-2020 07:09:03	Atique Salmani	New		-	01-07-2020 07:08:38	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
01-07-2020 07:42:22	Atique Salmani	Completed	out door camera installed and working ok.																						
01-07-2020 07:09:03	Atique Salmani	New		-																					
01-07-2020 07:08:38	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-08-2020 01:31:09</td><td>Atique Salmani</td><td>bhoomi a wing line not working cable break from floor duct to home so find out the cable and resolved the issue. working ok.</td></tr><tr><td>05-08-2020 04:39:17</td><td>Atique Salmani</td><td>cctv old cabling cut by mouse and find out the cable cable was cut from 4and 5 floor joind 2 mtr cable for 2cameras and working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-08-2020 01:31:09	Atique Salmani	bhoomi a wing line not working cable break from floor duct to home so find out the cable and resolved the issue. working ok.	05-08-2020 04:39:17	Atique Salmani	cctv old cabling cut by mouse and find out the cable cable was cut from 4and 5 floor joind 2 mtr cable for 2cameras and working ok.											
Date Time	Technician Name	Remark																							
06-08-2020 01:31:09	Atique Salmani	bhoomi a wing line not working cable break from floor duct to home so find out the cable and resolved the issue. working ok.																							
05-08-2020 04:39:17	Atique Salmani	cctv old cabling cut by mouse and find out the cable cable was cut from 4and 5 floor joind 2 mtr cable for 2cameras and working ok.																							